

FAA-PMA Parts Eligibility for **Continental** Engines

Click here and enter the Continental part number
you are searching for.

Note: If you do not know the part number,
click the button below.

Acrobat



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA1000	19	Continental Engines: C-125-2; C-145-2, 2H; C75-8, 12, 14, 16, 8F, 12F, 14F, 16F, C85-8, 12, 14, 16, 8F, 12F, 14F, 16F; C90-8, 12, 14, 16, 8F, 12F, 14F, 16F; O-200-A, B; O-300-A, B, C, D; GO-300-A, C, D, E, F
SA1004	16	Continental Engines: C125-2; C145-2, 2H; C75-8, 12, 14, 16, 8F, 12F, 14F, 16F; C85-8, 12, 14, 16, 8F, 12F, 14F, 16F; C90-8, 12, 14, 16, 8F, 12F, 14F, 16F; O-200-A, B; O-300-A, B, C, D; GO-300-A, C, D, E
SA1007	26	Continental Engines: C125-2; C145-2, 2H; C75-8, 12, 14, 16, 8F, 12F, 14F, 16F; C85-8, 12, 14, 16, 8F, 12F, 14F, 16F; C90-8, 12, 14, 16, 8F, 12F, 14F, 16F; O-200-A, B; O-300-A, B, C, D; GO-300-A, C, D, E, F
SA10200-A1	97	Continental Engines: C75-8, 12, 14, 16, 8F, 12F, 14F, 16F; C85-8, 12, 14, 16, 8F, 12F, 14F, 16F; C90-8, 12, 14, 16, 8F, 12F, 14F, 16F; O-200-A, B; C125-2; C145-2, 2H; O-300-A, B, C, D; GO-300-A, C, D, E, F
SA10200-A1 CK		Continental Engines: C75-8, 12, 14, 16, 8F, 12F, 14F, 16F; C85-8, 12, 14, 16, 8F, 12F, 14F, 16F; C90-8, 12, 14, 16, 8F, 12F, 14F, 16F; O-200-A, B; C125-2; C145-2, 2H; O-300-A, B, C, D; GO-300-A, C, D, E, F
SA10200-A20P		Continental Engines: O-200-A, B; C125-2; C145-2, 2H; O-300-A, B, C, D
SA10200-A20P CK		Continental Engines: O-200-A, B; C125-2; C145-2, 2H; O-300-A, B, C, D
SA10200-A21	97	Continental Engines: C75-8, 12, 14, 16, 8F, 12F, 14F, 16F; C85-8, 12, 14, 16, 8F, 12F, 14F, 16F
SA10200-A22	97	Continental Engines: C90-8, 12, 14, 16, 8F, 12F, 14F, 16F; C85-8, 12, 14, 16, 8F, 12F, 14F, 16F; C90-8, 12, 14, 16, 8F, 12F, 14F, 16F; O-200-A, B; C125-2; C145-2, 2H; O-300-A, B, C, D; GO-300-A, C, D, E, F
SA10200-A23	97	Continental Engines: GO-300-A, C, D, E, F
SA10202	97	Continental Engines: C75-8, 12, 14, 16, 8F, 12F, 14F, 16F; C85-8, 12, 14, 16, 8F, 12F, 14F, 16F; C90-8, 12, 14, 16, 8F, 12F, 14F, 16F; O-200-A, B; C125-2; C145-2, 2H; O-300-A, B, C, D; GO-300-A, C, D, E, F
SA10203	97	Continental Engines: C75-8, 12, 14, 16, 8F, 12F, 14F, 16F; C85-8, 12, 14, 16, 8F, 12F, 14F, 16F; C90-8, 12, 14, 16, 8F, 12F, 14F, 16F; O-200-A, B; C125-2; C145-2, 2H; O-300-A, B, C, D; GO-300-A, C, D, E, F



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA10204	97	Continental Engines: C75-8, 12, 14, 16, 8F, 12F, 14F, 16F; C85-8, 12, 14, 16, 8F, 12F, 14F, 16F; C90-8, 12, 14, 16, 8F, 12F, 14F, 16F; O-200-A, B; C125-2; C145-2, 2H; O-300-A, B, C, D; GO-300-A, C, D, E, F
SA10205	97	Continental Engines: C75-8, 12, 14, 16, 8F, 12F, 14F, 16F; C85-8, 12, 14, 16, 8F, 12F, 14F, 16F; C90-8, 12, 14, 16, 8F, 12F, 14F, 16F; O-200-A, B; C125-2; C145-2, 2H; O-300-A, B, C, D; GO-300-A, C, D, E, F
SA10206	97	Continental Engines: C75-8, 12, 14, 16, 8F, 12F, 14F, 16F; C85-8, 12, 14, 16, 8F, 12F, 14F, 16F; C90-8F, 12F, 14F, 16F; O-200-A, B; C125-2; C145-2, 2H; O-300-A, B, C, D; GO-300-A, C, D, E, F
SA10209	97	Continental Engines: C75-8, 12, 14, 16, 8F, 12F, 14F, 16F; C85-8, 12, 14, 16, 8F, 12F, 14F, 16F; C90-8, 12, 14, 16, 8F, 12F, 14F, 16F; O-200-A, B; C125-2; C145-2, 2H; O-300-A, B, C, D; GO-300-A, C, D, E, F
SA2000	23	Continental Engines: C-125-2; C145-2, 2H; C75-8, 12, 14, 16, 8F, 12F, 14F, 16F; C90-8, 12, 14, 16, 8F, 12F, 14F, 16F; O-200-A, B; O-300-A, B, C, D; GO-300-A, C, D, E, F
SA20202	54	Continental Engines: C125-2; C145-2, 2H; GO-300-A, C, D, E; GTSIO-520-C, D, F, H, K, L, M, N; IO-346 IO-360-A, AB, C, CB, D, DB, D15, DB15, G, GB, H, HB, J, JB, K, KB; IO-520-B, BA, BB, C, CB, M, MB; IO-550-A, B, C, G; LTSIO-360-E, EB, KB; O-300-A, B, C
SA2025	137	Continental Engines: C125-2; C145-2, 2H; O-200-A, B; O-300-A, B, C, D; IO-346; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; O-470-A, B, E, G, J, K, L, M, P, R, S, U; TSIO-470-B, C, D; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; TSIO-52
SA2026	77	Continental Engines: IO-470-C, D, E, F3, F4, F5, F7, G, H, J, K, K14, L, L8, M, N, R, S, V, F18, F19, F23 F26; O-470-B, G, K, L, M, P, R, S, U; TSIO-470-B; IO-520-A, D, E, F, J, K, L; TSIO-520-AE, C, G, H, M, P, R; LTSIO-520-AE; IO-550-G
SA2101	23	Continental Engines: C75-8, 12, 14, 16, 8F, 12F, 14F, 16F; C85-8, 12, 14, 16, 8F, 12F, 14F, 16F; C90-8, 12, 14, 16, 8F, 12F, 14F, 16F; O-200-A, B; O-300-A, B, C, D; GO-300-A, C, D, E, F
SA2102	23	Continental Engines: C75-8, 12, 14, 16, 8F, 12F, 14F, 16F; C85-8, 12, 14, 16, 8F, 12F, 14F, 16F; C90-8, 12, 14, 16, 8F, 12F, 14F, 16F; O-200-A, B; O-300-A, B, C, D; GO-300-A, C, D, E
SA2103	24	Continental Engines: C75-8, 12, 14, 16, 8F, 12F, 14F, 16F; C85-8, 12, 14, 16, 8F, 12F, 14F, 16F; C90-8, 12, 14, 16, 8F, 12F, 14F, 16F; C125-2; C-145-2, 2H; O-200-A, B; O-300-A, B, C, D; GO-300-A, C, D, E, F
SA2105	34	Continental Engines: C75-8, 12, 14, 16, 8F, 12F, 14F, 16F; C85-8, 12, 14, 16, 8F, 12F, 14F, 16F; C90-8, 12, 14, 16, 8F, 12F, 14F, 16F; C-125-2; C-145-2, 2H; O-200-A, B; O-300-A, B, C, D



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA21051	76	Continental Engines: A65, 75; C125-2; C145-2, 2H; C75, 85, 90; O-200-A, B; O-300-A, B, C, D
SA2106	25	Continental Engines: C125-2; C145-2, 2H; C75-8, 12, 14, 16, 8F, 12F, 14F, 16F; C85-8, 12, 14, 16, 8F, 12F, 14F, 16F; C90-8, 12, 14, 16, 8F, 12F, 14F, 16F; O-200-A, B; O-300-A, B, C, D; GO-300-A, C, D, E, F
SA2107	32	Continental Engines: C125-2; C145-2, 2H; C75-8, 12, 14, 16, 8F, 12F, 14F, 16F; C85-8, 12, 14, 16, 8F, 12F, 14F, 16F; C90-8, 12, 14, 16, 8F, 12F, 14F, 16F; O-200-A, B; O-300-A, B, C, D; GO-300-A, C, D, E, F
SA21114	97	Continental Engines: C75-8, 12, 14, 16, 8F, 12F, 14F, 16F; C85-8, 12, 14, 16, 8F, 12F, 14F, 16F; C90-8, 12, 14, 16, 8F, 12F, 14F, 16F; O-200-A, B; C125-2; C145-2, 2H; O-300-A, B, C, D; GO-300-A, C, D, E, F; E165-2; E185-1, 3, 8, 9, 11; E225-4, 8
SA21153	1	Continental Engines: O-300-A, B, C, D; GO-300-A, C, D, E; C-75, 85, 90; O-200-A, B; A65; A-75; C125-2; C145-2, 2H
SA21185		Continental Engines: A65, 75; C75, 85, 90; O-200-A, B
SA21218	102	Continental Engines: C-75, 85, 90; O-200-A, B
SA21247	102	Continental Engines: TSIO-470-B1, B2, B3, C, D
SA21284	90	Continental Engines: A65, A75; C-125-2; C-145-2, 2H; C75, C85, C90; GO-300-A, C, D, E; O-200-A, B; O-300-A, B, C, D
SA21323	76	Continental Engines: C-125-2; C-145-2, 2H; O-300-A, B, C, D; C-75, 85, 90; O-200-A, B; A-65, 75
SA21361	14	Continental Engines: A65; A75; C125-2; C145-2, 2H; C75; C85; C90; GO-300-A, C, D, E; O-300-A, B, C, D; O-200-A, B
SA21477	78	Continental Engines: A65, A75; C125-2; C145-2, 2H; GO-300-A, C, D, E; IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; LTSIO-360-E, EB, KB; O-200-A, B; O-300-A, B, C, D; TSIO-360-A, AB, B, C, CB, D, DB, E, EB, F, FB, G, GB, H, HB, JB, KB, LB, MB



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA22022	78	Continental Engines: A65; A75; C125-2; C145-2, 2H; C75; C85; C90; GO-300-A, C, D, E; IO-346; IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; IO-470-J, K; LTSIO-360-E, EB, KB; O-200-A, B; O-300-A, B, C, D; O-470-A, E, J; TSIO-360-A, B, C, D, DB, E
SA22133	90	Continental Engines: A65, A75; C75, C85, C90; C-125-2
SA22139	78	Continental Engines: A65, A75; IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; IO-550-G; LTSIO-360-E, KB; TSIO-360-A, AB, B, C, CB, D, DB, E, EB, F, FB, GB, H, HB, JB, KB, LB, MB; TSIO-520-BE
SA22250	76	Continental Engines: C125-2; C145-2, 2H; C75, 85, 90; GO-300-A, C, D, E; O-200-A, B; O-300-A, B, C, D
SA22344	76	Continental Engines: C-75, C85, C90; O-200-A, B
SA22350	76	Continental Engines: C-75, C85, C90; O-200-A, B
SA22354	97	Continental Engines: C75-8, 12, 14, 16, 8F, 12F, 14F, 16F; C85-8, 12, 14, 16, 8F, 12F, 14F, 16F; C90-8, 12, 14, 16, 8F, 12F, 14F, 16F; O-200-A, B; C75-8, 12, 14, 16, 8F, 12F, 14F, 16F; C85-8, 12, 14, 16, 8F, 12F, 14F, 16F; C90-8, 12, 14, 16, 8F, 12F, 14F
SA22355	97	Continental Engines: C75-8, 12, 14, 16, 8F, 12F, 14F, 16F; C85-8, 12, 14, 16, 8F, 12F, 14F, 16F; O-200-A, B
SA22387	90	Continental Engines: A65; A75; C75; C85; C90; O-200-A, B
SA22532	97	Continental Engines: C75-8, 12, 14, 16, 8F, 12F, 14F, 16F; C85-8, 12, 14, 16, 8F, 12F, 14F, 16F; C90-8, 12, 14, 16, 8F, 12F, 14F, 16F; O-200-A, B; C125-2; C145-2, 2H; O-300-A, B, C, D; GO-300-A, C, D, E, F
SA22534	97	Continental Engines: C75-8, 12, 14, 16, 8F, 12F, 14F, 16F; C85-8, 12, 14, 16, 8F, 12F, 14F, 16F; C90-8, 12, 14, 16, 8F, 12F, 14F, 16F; O-200-A, B; C125-2; C145-2, 2H; O-300-A, B, C, D; GO-300-A, C, D, E, F; E165-2; E185-1, 3, 8, 9, 11; E225-4, 8
SA22535	78	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-346; IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, C5, C6, C7, CB, CB10, CB11, CB6, CB7, CB8, CB9, D, E, F,



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA22537	78	Continental Engines: A65, A75; C125-2; C145-2, 2H; C75, C85, C90; LTSIO-360-E, EB, KB; O-200-A, B; O-300-A, B, C, D; O-470-A; TSIO-360-A, AB, B, C, CB, D, DB, E, EB, F, FB, GB, H, HB, JB, KB, LB, MB
SA2265	54	Continental Engines A65; A75; C-125-2; C-145-2, 2H; GO-300-A, C, D, E; GTSIO-520-C, D, F, H, K, L, M, N; IO-346; IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; IO-470-C, H, J, K, N; IO-520-B, BA, BB, C, CB, M, MB; IO-550-A, B, C, G
SA22800	102	Continental Engines: A65; A75; C75; C85; C90; O-200-A, B; C-125; C-145-2, 2H; O-300-A, B, C, D
SA22949	1	Continental Engines: C-75; C-85; C-90; C125-2; C145-2, 2H; O-200-A, B; O-300-A, B, C, D
SA23410	97	Continental Engines: C75-8, 12, 14, 16, 8F, 12F, 14F, 16F; C85-8, 12, 14, 16, 8F, 12F, 14F, 16F; C90-8, 12, 14, 16, 8F, 12F, 14F, 16F; O-200-A, B; C125-2; C145-2, 2H; O-300-A, B, C, D
SA23411	137	Continental Engines: O-300-A, B, C, D; C145-2, 2H; C125-2
SA24024	1	Continental Engines: C-75; C-85; O-200; GO-300; C-90
SA24026	78	Continental Engines: A65; A75; C125-2; C145-2, 2H; C75; C85; C90; GO-300-A, C, D, E; IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; LTSIO-360-E, EB, KB; O-200-A, B; O-300-A, B, C, D; TSIO-360-A, AB, B, C, CB, D, DB, E, EB, F, FB, GB, H, HB, JB,
SA24029	1	Continental Engines: C-75; C-85; C-90; C-125-2; C145-2, 2H; O-200-A, B; O-300-A, B, C, D
SA24031	1	Continental Engines: C-90; C125-2; C145-2, 2H; O-200-A, B; O-300-A, B, C, D
SA24044	97	Continental Engines: C75-8, 12, 14, 16, 8F, 12F, 14F, 16F; C85-8, 12, 14, 16, 8F, 12F, 14F, 16F; C90-8, 12, 14, 16, 8F, 12F, 14F, 16F; O-200-A, B; C125-2; C145-2, 2H; O-300-A, B, C, D; GO-300-A, C, D, E, F
SA24047	1	Continental Engines: O-300; O-200; C-85; C-90; C-115; C-125; C-145



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA24122	1	Continental Engines: C-75; C-85; C-90; A-65; A-75; C-125-2; C145-2, 2H; GO-300-A, C, D, E; O-200-A, B; O-300-A, B, C, D
SA24239	102	Continental Engines: O-470-A, B, E, G, J, K, L, M, P, R, S, U; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; TSIO-470-B, C, D; IO-520-A, BA, C, D, E, F, J, K, L, M; TSIO-520-C, G, H, M, P, R, T, AF, BE, B, BB, D, DB, E, EB, J, JB, K, KB, L, LB,
SA24252	102	Continental Engines: A65; A75; C75; C85; C90; O-200-A, B
SA2437	137	Continental Engines: O-300-B, C, D; TSIO-470-B Spec 1, Spec 2, Spec 3; A65, 75; GO-300-A, C, D, E; C145-2, 2H; C125-2; E165-2; E185-1, 3, 8, 9, 11; E225-4, 8
SA2439	137	Continental Engines: A65, 75; C75, 85, 90; O-200-A, B; C-125-2; C-145-2, 2H; O-300-A, B, C, D; GO-300-A, C, D, E; IO-346-A; E-165-2; E-185-1, 3, 8, 9, 11; E-225-4, 8; IO-360-A, C, D, G, H, J, K, AB, BB, CB, DB, HB, JB, KB; TSIO-360-A, AB, B, C, CB, D, DB
SA2441	77	Continental Engines: A65; A75; C125-2; C145-2, 2H; C75; C85; C90; GO-300-A, C, D, E; GTSIO-520-C, D, F, H, K, L, M, N; IO-346; IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; IO-470-C, D, E, F, G, H, J, K, L, L15, L19, L21, L22, M, N, N12, N3, P,
SA2471	77	Continental Engines: A65; A75; C145-2H; C75; C85; C90; IO-470-D, L, M, N10, N11, N12, P, S, U, V; IC 520-A, C, CB, D, E, F, J, K, L, M, MB; IO-550-A, B, C, D, E, F, L; O-200-A, B; O-300-B; O-470-B, E, M, R, S, U; TSIO-470-B-2, B3, C, D; TSIO-520-AF, B, B
SA2472	54	Continental Engines: C90; GTSIO-520-C, D, F, H, K, L, M, N; IO-346; IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, F16, J, K, L, M, MB; IO-550-A, B, C, D
SA2473	54	Continental Engines: A65; A75; C125-2; C145-2, 2H; C75; C85; C90; GO-300-A, C, D, E; GTSIO-520-C, D, F, H, K, L, M, N; IO-346; IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; IO-470-C, D, E, F, G, H, J, K, K14, L, M, N, N3, P, R, S, U, V; IO-520-
SA24759	76	Continental Engines: C-125, 145; O-300 All Models
SA24764	54	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-346; IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-A, B, C, D, E, F, G,
SA24770	97	Continental Engines: C75-8, 12, 14, 16, 8F, 12F, 14F, 16F; C85-8, 12, 14, 16, 8F, 12F, 14F, 16F; C125-2; C145-2; O-300-A, C, D; E165-2; IO-346-A, A65, A75



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA24802	54	Continental Engines: E225-4, 8
SA24804	14	Continental Engines: A65; A75; C125-2; C145-2, 2H; C75, 85, 90; O-200-A, B; O-300-A, B, C, D
SA24835	77	Continental Engines: IO-346; IO-470-C, D, E, F, F19, F3, F4, F7, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, BA, C, D, E, F, F12, F16, F3, F4, J, K, L, M, MB; IO-550-A, B, C, D, E, F, L; LTSIO-520-AE; O-470-A, B, E, G, J, K, K17, L, L16, M, P, R, R14,
SA24856	76	Continental Engines: E165-2; E185-1, 3, 8, 9, 11; E225-4, 8
SA24878A	101	Continental Engines: C125-2; C-75, 85, 90; IO-360-A, C, D, G, H, J, K; IO-520-BA, BB, C, CB; O-200-A, B, O-300-A, B, C, D; C-145-2, 2H; TSIO-520-B, BE, D, E, J, K, L, N, UB, VB, WB; GO-300-A, C, D, E; IO-550-A, B, C, G; TSIOL-550-A
SA25135	76	Continental Engines: O-470-B, E, M; E165-2; E185-1, 3, 8, 9, 11; E225-4, 8
SA25328	76	Continental Engines: C125-2; C145-2, 2H; O-300-A, B, C, D; TSIO-470-B1, B2, B3, C, D
SA25369	1	Continental Engines: C-75; C-85; A-65; C125-2
SA3364	78	Continental Engines: IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; LTSIO-360-E, EB, KB; TSIO-360-A, B, C, D, E, F, G, GB, H, JB, KB, LB
SA3365	78	Continental Engines: IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; LTSIO-360-E, EB, KB; TSIO-360-A, B, C, D, E, F, G, GB, H, JB, KB, LB
SA35019	76	Continental Engines: C75, C85, C90; O-200-A, B
SA350997	1	Continental Engines: O-470; TSIO-470



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA350998	54	Continental Engines: IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-A, B, C, D, E, F, G, L; O-470-A, B, E, G, J, K, L, M, P, R, S, U; TSIO-470-B1, B2, B3, C, D; TSIO-520-AE, AF, B, BB, B
SA352058	90	Continental Engines: E165-2; E185-1, 3, 8, 9; E225-4, 8
SA352059	76	Continental Engines: E165-2; E185-1, 3, 8, 9; E225-4, 8
SA352061	76	Continental Engines: E165-2; E185-1, 3, 8, 9; E225-4, 8
SA352062	76	Continental Engines: E165-2; E185-1, 3, 8, 9; E225-4, 8
SA352063	76	Continental Engines: E185-1, 8, 11; E225-8
SA352064	76	Continental Engines: E185-1, 8, 11; E225-8
SA352065	90	Continental Engines: E165-2; E185-1, 3
SA352066	76	Continental Engines: IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; LTSIO-360-E, EB, KB; TSIO-360-A, AB, B, C, CB, D, DB, E, EB, F, FB, G, GB, H, HB, JB, KB, LB, MB; E165-2; E185-1, 3, 8, 9, 11; E225-4, 8
SA352067	76	Continental Engines: O-470-7; E165-2; E185-1, 3, 8, 9, 11; E225-4, 8
SA352069	76	Continental Engines: E165-2; E185-1, 3, 8, 9, 11; E225-4, 8
SA352179	90	Continental Engines: C125-2; C145-2, 2H; C75, C85, C90; GO-300-A, C; O-200-A, B; O-300-A, B, C



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA35562	43	Continental Engines: C125-2; C145-2, 2H; O-300-A, B, C, D
SA35563	43	Continental Engines: C125-2; C145-2, 2H; O-300-A, B, C, D
SA35636	14	Continental Engines: C75; C85; C90; C125; O-300-A; GO-300-A; O-200-A
SA3577	76	Continental Engines: A65, 75; C75, 85, 90; O-200-A, B
SA35897	1	Continental Engines: O-300; GO-300; C-75, 85; C-90; C-125; A-65; A-75; O-200; IO-360; TSIO-360
SA35923	76	Continental Engines: A65, A75; C75, C85, C90; O-200-A, B
SA35966	1	Continental Engines: IO-470-J, K; IO-346-A, B; O-470-A, B, E, J, 2, 4, 11, 15, 13A; FSO-470-A; E-185, 1, 3, 8, 9, 11; E-225-4, 8
SA35967	54	Continental Engines: E185-1, 3, 8, 9, 11; E225-4, 8
SA35971	54	Continental Engines: IO-346; IO-550-D, E, F, L; TSIO-470-B1, B2, B3, C, D; E165-2; E185-1, 3, 8, 9, 11; E225-4, 8; O-470-A, B, E, G, J, K, L, M, P, R, S, U; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, BA, C, D, E, G, H, J, K, L, M,
SA35972	35	Continental Engines: IO-346; TSIO-470-B1, B2, B3, C, D; O-470-A, B, E, G, J, K, L, M, P, R, S, U; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; E165-2; E185-1, 3, 8, 9, 11; E225-4, 8
SA35985	76	Continental Engines: IO-470-B, C, E, H, J, M; LTSIO-360-E, EB, KB; O-470-A, B, E, G, J, K, L, M, P, R, S, U; TSIO-360-A, AB, B, E, F, FB, G, GB, H, JB, KB, LB; E165-2; E185-1, 3, 8, 9, 11; E225-4, 8
SA36027	76	Continental Engines: E165-2; E185-1, 3, 8, 9, 11; E225-4, 8



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA36050	76	Continental Engines: C125-2; C145-2, 2H; O-300-A, B, C, D
SA36066	97	Continental Engines: C75-8, 12, 14, 16, 8F, 12F, 14F, 16F; C85-8, 12, 14, 16, 8F, 12F, 14F, 16F; C90-8, 12, 14, 16, 8F, 12F, 14F, 16F; O-200-A, B
SA36100	76	Continental Engines: C125-2; C145-2, 2H; GO-300-A, C, D, E; O-300-A, B, C, D
SA36151	77	Continental Engines: IO-346; TSIO-470-B1, B3, C, D; IO-470-C, D, E, F, G, H, L, M, N, P, R, S, U, V; IC 520-A, BA, C, E, F, J, K, L, M, MB; TSIO-520-AF, B, C, D, E, G, H, M, P, R, J, K, L, N, UB, VB, WB; IO-550-A, B, C; O-470-K, L, R, S, U; A65; A75; C75
SA36151-L		Continental Engines: IO-346; TSIO-470-B1, B3, C, D; IO-470-C, D, E, F, G, H, L, M, N, P, R, S, U, V; IC 520-A, BA, C, E, F, J, K, L, M, MB; TSIO-520-AF, B, C, D, E, G, H, M, P, R, J, K, L, N, UB, VB, WB; IO-550-A, B, C; O-470-K, L, R, S, U; A65; A75; C75
SA36151-N		Continental Engines: IO-346; TSIO-470-B1, B3, C, D; IO-470-C, D, E, F, G, H, L, M, N, P, R, S, U, V; IC 520-A, BA, C, E, F, J, K, L, M, MB; TSIO-520-AF, B, C, D, E, G, H, M, P, R, J, K, L, N, UB, VB, WB; IO-550-A, B, C; O-470-K, L, R, S, U; A65; A75; C75
SA36170	1	Continental Engines: C125-2; C145-2; O-300-A, C, D
SA36171	1	Continental Engines: C125-2; C145-2, 2H; O-300-A, B, C, D
SA3920	1	Continental Engines: O-300; O-200; C-85; C-90; C-115; C-125; C-145
SA3921	1	Continental Engines: C-85; C-90; C-125; C-145
SA3923	1	Continental Engines: C-75
SA4001	29	Continental Engines: O-470-A, B, E, G, J, K, L, M, P, 4, 7B, 11, 13, 13A; IO-470-C, J, K; LIO-470-A; E185-13, 8, 9, 11; E225-4, 8



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA4003	35	Continental Engines: TSIO-470-B, C, D; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; O-470-A, B, E, G, J, K, L, M, P, R, S, U, 4, 7B, 13, 13A; LIO-470-A; E185-1, 3, 8, 9, 11; E225-4, 8
SA401507	77	Continental Engines: C125-2; C145-2; C75; C85; C90; GO-300-A, C, D, E; GTSIO-520-C, D, F, H, K, L, M, N; IO-346; IO-360-A, C, D, G, H, J, K; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V, V10, V2, V8; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L,
SA401804	54	Continental Engines: A65; A75; C125-2; C145-2, 2H; C75; C85; C90; GO-300-A, C, D, E; GTSIO-520-C, D, F, H, K, L, M, N; IO-346; IO-470-C, H, J; IO-520-B, BA, BB, CB, M, MB; IO-550-A, B, C, G, L; O-200-A, A2, A23, A36, A57, B; O-300-A, B, C, D; O-470-B, G,
SA401814	78	Continental Engines: GO-300-A, C, D, E; GTSIO-520-C, D, F, H, K, L, M, N; IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; IO-470-P; IO-520-B, BA, BB, C, CB, M, MB; IO-550-A, B, C, G; LTSIO-360-E, EB, KB; O-470-B, E, P, R32; TSIO-360-A, AB, B, C,
SA401870	97	Continental Engines: C75-8, 12, 14, 16, 8F, 12F, 14F, 16F; C85-8, 12, 14, 16, 8F, 12F, 14F, 16F; C90-8, 12, 14, 16, 8F, 12F, 14F, 16F; O-200-A, B; C125-2; C145-2, 2H; O-300-A, B, C, D; GO-300-A, C, D, E, F; IO-360-C, G; LTSIO-360-E, KB; TSIO-360-A, B, C,
SA401885	78	Continental Engines: A65; A75; GTSIO-520-C, D, F, H, K, L, M, N; IO-346; IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, DB, E, EB, F, J, JB, K, KB, L, LB, M, M
SA401893	102	Continental Engines: O-470-G, K, L, M, P, R, S, U; IO-470-C, D, E, F, G, H, L, M, N, P, R, S, U, V; TSIC 470-B, C, D; IO-520-A, BA, C, D, E, F, J, K, L, M; TSIO-520-B, D, E, DB, EB, BE; GTSIO-520-C, D, F, H, K, L, M; TSIO-520-C, G, H, M, R, T
SA402044	78	Continental Engines: A65; A75; C125-2; C145-2, 2H; C75; C85; C90; IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; LTSIO-360-E, EB, KB; O-200-A, A57, B; O-300-A, B; TSIO-360-A, AB, B, C, CB, D, DB, E, EB, F, FB, GB, H, HB, JB, KB, LB, MB; TSIO-520
SA402151	54	Continental Engines: C125-2; C145-2, 2H; C75; C85; C90; GO-300-A, C, D, E; GTSIO-520-C, D, H, L, M, N; IO-346; IO-360-A, AB, C, CB, D, DB, EB, FB, G, GB, H, HB, J, JB, K, KB; IO-470-C, D, E, F, G, H, J, K, L, M, N, R, S, U, V; IO-520-A, B, BA, BB, C, CB,
SA40644	1	Continental Engines: E-185-1; E-225-B
SA4577	90	Continental Engines: A65, A75; C75, C85, C90
SA4700	1	Continental Engines: O-470-A, E, G, J, K, L, R, M, P, 4, 7B, 11, 13, 13A; IO-470-C, J, K; LIO-470-A; E185-1, 3, 8, 9, 11; E225-4, 8



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA47000L	147	Continental Engines: O-470-U; IO-470-D, E, F, H, L, LO, M, N, S, U, V
SA47000LCK	147	Continental Engines: O-470-U; IO-470-D, E, F, H, L, LO, M, N, S, U, V
SA47000S	147	Continental Engines: O-470-G, K, L, M, P, R, S; IO-470-C, G, P, R
SA47000SCK	147	Continental Engines: O-470-G, K, L, M, P, R, S; IO-470-C, G, P, R
SA4701	1	Continental Engines: IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; O-470-A, B, E, G, J, K, L, M, P, R, S, U, 4, 7B, 11, 13, 13A; LIO-470-A; TSIO-470-B, C, D; E185-1, 3, 8, 9, 11; E225-4, 8
SA47030-P15	166	Continental Engine: O-470-G, K, L, M, P, R, S, U; IO-470-C, D, E, F, G, H, L, M, N, P, R, S, U, V
SA4705	63	Continental Engines: IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, T, U, V; O-470-A, B, E, G, J, K, L, M, P, R, S, U, 4, 7B, 11, 13, 13A; TSIO-470-B, C, D; E185-1, 3, 8, 9, 11; E225-4, 8
SA4706A	77	Continental Engines: IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; O-470-A, B, E, G, J, K, L, M, P, R, S, U, 4, 7B, 11, 13, 13A
SA4707	29	Continental Engines: E165-2; E185-1, 3, 8, 9, 11; E225-4, 8; O-470-A, E, G, J, 4, 7B, 11, 13, 13A, K, L, R, M, U; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; LIO-470-A; TSIO-470-B, C, D
SA4708	56	Continental Engines: O-470 and IO-470 Series
SA4709	35	Continental Engines: IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, T, U, V; O-470-A, B, E, G, J, K, L, M, P, R, S, U, 4, 7B, 11, 13, 13A; TSIO-470-B, C, D; LIO-470-A; TSIO-470-B, C, D; E185-1, 3, 8, 9, 11; E225-4, 8
SA5001	45	Continental Engines: IO-520-M; TSIO-520-M, N, P, R



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA5002	45	Continental Engines: 520-M, N, P, R
SA5003	36	Continental Engines: IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; TSIO-520-B, BE, D, J, K, L, N, UB, VB, WB, AE, AF, C, CE, G, H, M, P, R, T, U, BB, DB, EB, JB, KB, LB, NB; GTSIO-520-C, D, F, G, H, K, L, M, N; TSIOL-550-A; LTSIO-520-AE;
SA5003A	54	Continental Engines: IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; TSIO-520-B, BE, D, E, J, K, L, N, UB, VB, WB, AE, AF, C, CE, G, H, M, P, R, T, U, BB, DB, EB, JB, KB, LB, NB; GTSIO-520-C, D, F, G, H, K, L, M, N; IO-550-A, B, C, D, E, F, G, L; TS
SA5004	44	Continental Engines: IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; TSIO-520-B, BE, D, E, J, K, L, N, UB, VB, WB, AF, C, CE, G, H, M, P, R, T, BB, CE, DB, EB, JB, U, KB, LB, NB; GTSIO-520-C, D, F, G, H, K, L, M, N; IO-550-A, B, C, D, E, F, G, L; TS
SA5004A	54	Continental Engines: IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; TSIO-520-B, BE, D, E, J, K, L, N, UB, VB, WB, AE, AF, C, CE, G, H, M, P, R, T, U, BB, DB, EB, JB, KB, LB, NB; GTSIO-520-C, D, F, G, H, K, L, M, N; IO-550-A, B, C, D, E, F, G, L; TS
SA501867	78	Continental Engines: GO-300-D, E; GTSIO-520-C, D, F, H, K, L, M, N; IO-346; IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-A, B, C
SA515152	1	Continental Engines: O-470-13A, 15, 2, A, J, E, 11; E-185-1, 9, 11, 8, 3; E-225-4, 8; GSO-526-A; IO-346-A, B; IO-470-J, K
SA52000	147	Continental Engines: IO-520-A, B, BA, C, D, E, F, J, K, L, M, BB, CB, MB; IO-550-A, B, C; TSIO-520-AF, B, BB, C, CE, D, DB, E, EB, G, H, J, JB, K, KB, L, LB, M, N, NB, P, R, T, UB, VB, WB
SA52000-A1		Continental Engines: IO-520-A, B, BA, C, D, E, F, J, K, L, M, N, BB, CB, MB, NB; IO-550-A, B, C, D, F, G, L; TSIO-520-A, AE, AF, B, BB, BE, C, CE, D, DB, E, EB, G, H, J, JB, K, KB, L, LB, M, N, NB, P, R, T, UB, VB, WB; LTSIO-520-AE
SA520004	76	Continental Engines: E165-2; E185-1, 3, 8, 9, 11; E225-4, 8
SA52000CK	147	Continental Engines: IO-520-A, B, BA, C, D, E, F, J, K, L, M, BB, CB, MB; IO-550-A, B, C; TSIO-520-AF, B, BB, C, CE, D, DB, E, EB, G, H, J, JB, K, KB, L, LB, M, N, NB, P, R, T, UB, VB, WB
SA520046	101	Continental Engines: IO-520-A, BA, BB, C, CB, D, E, F, J, K, L, M, MB; TSIO-520-B, C, D, E, G, H, J, K, L, M, N, P, R, T, UB, VB, WB; GTSIO-520-C, D, F, H, K, L, M, N; IO-550-A, B, C, D, E, F, G, L; IO-346



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA5201	54	Continental Engines: IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-B, C, D, E, F, L; TSIO-52 B, C, D, E, G, H, J, K, L, M, N, P, R, T, BB, BE, CE, DB, EB, JB, KB, LB, NB, U, UB, VB, WB, AE, AF; GTSIO-520-C, D, F, G, H, K, L, M, N; LTSIO-52
SA520105	1	Continental Engines: IO-346; TSIO-470-B1, B2, B3, C, D; O-470-A, E, J, B, G, K, L, M, R, P; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, T, U, V; E165-2; E185-1, 3, 8, 9, 11; E225-4, 8
SA520106	1	Continental Engines: O-470; IO-470; E-185; E-225; IO-346; TSIO-470
SA520112	97	Continental Engines: C75-8, 12, 14, 16, 8F, 12F, 14F, 16F; C85-8, 12, 14, 16, 8F, 12F, 14F, 16F; C90-8, 12, 14, 16, 8F, 12F, 14F, 16F; O-200-A, B; C125-2; C145-2, 2H; O-300-A, B, C, D; GO-300-A, C, D, E, F; A65, A75; E165-2; E185-1, 3, 8, 9, 11; E225-4,
SA520129	147	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-470-C, D, E, F, G, H, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-A, B, C, G; O-470-B, G, K, L, M, P, R, S, U; TSIO-470-B1, B2, B3, C, D; TSIO-520-AF, B, BB
SA5201C	147	Continental Engines: IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-B, C, D, E, F, L; TSIO-52 B, C, D, E, G, H, J, K, L, M, N, P, R, T, BB, BE, CE, DB, EB, JB, KB, LB, NB, U, UB, VB, WB, AE, AF; LTSIO-520-AE
SA5202	54	Continental Engines: IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-B, C, D, E, F, L; TSIO-52 B, C, D, E, G, H, J, K, L, M, N, P, R, T, BB, BE, CE, DB, EB, JB, KB, LB, NB, U, UB, VB, WB, AE, AF; GTSIO-520-C, D, F, G, H, K, L, M, N; LTSIO-52
SA5202C	147	Continental Engines: IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-B, C, D, E, F, L; TSIO-52 B, C, D, E, G, H, J, K, L, M, N, P, R, T, BB, BE, CE, DB, EB, JB, KB, LB, NB, U, UB, VB, WB, AE, AF; TSIO-520-AE
SA5203	18	Continental Engines: GTSIO-520
SA52030-P15	166	Continental Engine: IO-520-A, B, BA, C, D, E, F, J, K, L, M, BB, CB, MB; IO-550-A, B, C; TSIO-520-AF, B, BB, C, CE, D, DB, E, EB, G, H, J, JB, K, KB, L, LB, M, N, NB, P, R, T, UB, VB, WB
SA5205	54	Continental Engines: IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-B, C, D, E, F, L; TSIO-52 B, C, D, E, G, H, J, K, L, M, N, P, R, T, BB, BE, CE, DB, EB, JB, KB, LB, NB, U, UB, VB, WB, AE, AF; GTSIO-520-C, D, F, G, H, K, L, M, N; LTSIO-52
SA5205A	95	Continental Engines: IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-B, C, D, E, F, L; TSIO-52 B, C, D, E, G, H, J, K, L, M, N, P, R, T, BB, BE, CE, DB, EB, JB, KB, LB, NB, U, UB, VB, WB, AE, AF; GTSIO-520-C, D, F, G, H, K, L, M, N; LTSIO-52



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA5207	63	Continental Engines: IO-520-A, BA, BB, C, CB, D, E, F, J, K, L, M, MB; TSIO-520-B, BB, C, D, DB, E, EB, G, H, J, JB, K, KB, L, LB, M, N, NB, P, R, T, U, UB, VB, WB
SA5208	66	Continental Engines: IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; TSIO-520-B, BE, C, D, J, K, L, N, M, P, UB, VB, WB, AF, C, CE, G, H, R, T, U, V, AE, BB, DB, EB, VB, WB, JB, KB, UB, LB, NB; GTSIO-520-C, D, F, H, K, L, M, N; IO-550-A, B, C, D, E,
SA5209	54	Continental Engines: IO-346; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; TSIO-520-B, BE, D, E, J, K, L, N, M, P, UB, VB, WB, AF, C, CE, G, H, R, T, U, BB, DB, EB, JB, KB, LB, NB; GTSIO-520-C, D, F, H, K, L, M, N; IO-550-A, B, C, D, E, F, G, L; T
SA5209A	54	Continental Engines: IO-346; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; TSIO-520-B, BE, D, E, J, K, L, N, UB, VB, WB, AF, C, CE, G, H, M, P, R, T, U, BB, DB, EB, JB, KB, LB, NB; GTSIO-520-C, D, F, G, H, K, L, M, N; IO-550-A, B, C, D, E, F, G, L
SA524818	54	Continental Engines: IO-346; IO-520-B, BA, BB, C, CB, M, MB; IO-550-A, B, C, G; TSIO-520-B, BB, BE, D, DB, E, EB, J, JB, K, KB, L, LB, N, NB, U, UB, VB, WB; TSIOL-550-A
SA530011	76	Continental Engines: C125-2; C145-2, 2H; O-300-A, B, C, D
SA530019		Continental Engines: A65, A75; C75, C85, C90; O-200-A, B
SA530058	1	Continental Engines: A-65; A-75; C-75; C-85; C-90; O-200-A, B
SA530162	76	Continental Engines: A65, A75; C125-2; C145-2, 2H; C75, C85, C90; GO-300-A, C, D, E; O-200-A, B; O-300-A, B, C, D
SA530162-S	76	Continental Engines: A65; A75; C125-2; C145-2, 2H; C75; C85; C90; GO-300-A, C, D, E; O-200-A, B; O-300-A, B, C, D
SA530192	1	Continental Engines: C125; C145-2, 2H; C90; O-200-A, B; O-300-A, B, C, D
SA530213	38	Continental Engines: C-75; C-85; C-90; O-200; C-125; C-145; O-300; GO-300; IO-360; TSIO-360; LTSIO-360



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA530340	76	Continental Engines: E165-2; E185-1, 3, 8, 9, 11; E225-4, 8
SA530341	76	Continental Engines: E165-2; E185-1, 3, 8, 9, 11; E225-4, 8
SA530346	54	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-346; IO-470-D, E, F, G, L, L15, L19, L21, L22, M, N12, P, R, S, U, V, V6; IO-520-A, C, CB, D, D10, D15, E, E3, E6, F, F7, J, K, L, M, MB; IO-550-A, C, D, E, F, G, L; LTSIO-520-AE, AE3, O-470-A, B,
SA530348		Continental Engines: C145-2, 2H; C90; O-200-A, B; O-300-A, B, C, D
SA530367	1	Continental Engines: IO-346; IO-470-J, K; LTSIO-520-AE; O-470-A, E, J; TSIO-520-AE; E165-2; E185-1, 3, 8, 9, 11; E225-4, 8
SA530383	1	Continental Engines: IO-470-C, G, J, K, P, R; O-470-A, B, E, G, J, K, L, M, P, R; E165-2; E185-1, 3, 8, 9, 11; E225-4, 8
SA530386	1	Continental Engines: O-470; IO-470; E-185, E-225; GSIO-470; TSIO-470
SA530462	1	Continental Engines: IO-470-J, K; O-470-A, E, J
SA530516	14	Continental Engines: O-300-B
SA530523	76	Continental Engines: C145-2H; O-300-B
SA530642	76	Continental Engines: A65, A75; C125-2; C145-2, 2H; C75, C85, C90; O-300-A, B, C, D
SA530658	54	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-346; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-A, B, C, D, E, F, G, L; O-470-A, B, E, G, J, K, L, M, P, R, S, U; TSIO-470-B



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA530828		Continental Engines: C-75, 85, 90, 125, 145; E-233, E-236; O-200; E-252, E-253; O-300-A, B, C, D
SA530829		Continental Engines: C-75, 85, 90, 125, 145; E-233, E-236; O-200; E-252, E-253; O-300-A, B, C, D
SA530830	3	Continental Engines: C125-2; C145-2, 2H; C75; C85; C90; O-200-A, B; O-300-A, B, C, D
SA530844	1	Continental Engines: O-470; IO-470; E-225; FSO-470; TSIO-470
SA530851	1	Continental Engines: C125-2; C145-2, 2H; C90; GO-300-A, C, D, E; O-200-A, B; O-300-A, B, C, D
SA530917	90	Continental Engines: C125-2; C145-2, 2H; IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; LTSIO 360-E, EB, KB; O-300-A, B, C, D; TSIO-360-A, AB, B, C, CB, D, DB, E, EB, F, FB, GB, H; GO-300-A, C, D, E
SA530928	76	Continental Engines: A65, A75; C125-2; C145-2, 2H; C75, C85, C90; GO-300-A, C, D, E; O-200-A, B; O-300-A, B, C, D
SA530940	97	Continental Engines: C75-8, 12, 14, 16, 8F, 12F, 14F, 16F; C85-8, 12, 14, 16, 8F, 12F, 14F, 16F; C90-8, 12, 14, 16, 8F, 12F, 14F, 16F; O-200-A, B; C125-2; C145-2, 2H; O-300-A, B, C, D; GO-300-A, C, D, E, F; A65, A75; E165-2; E185-1, 3, 8, 9, 11; E225-4,
SA531001	54	Continental Engines: C125-2; C145-2, 2H; C75; C85; C90; GO-300-A, C, D; GTSIO-520-C, D, F, H, K, L, M, N; IO-346; IO-360-A, C, D, G, H, J, K; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, L12, L13, M
SA531003	38	Continental Engines: C-75; C-85; C-90; O-200; E-165; E-185; E-225; C-125; C-145; O-300; GO-300; IO-360; TSIO-360; LTSIO-360; IO-346; IO-520; TSIO-520; GTSIO-520
SA531015	51	Continental Engines: C-145-2, 2H; O-300-A, E
SA531128	1	Continental Engines: E165-2; E185-1, 3, 8, 9, 11; E225-4, 8



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA531178	54	Continental Engines: GTSIO-C, D, F, H, K, L, M, N; IO-346; IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-A, B, C, D, E, F, G, L;
SA531378	54	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-470-D, L, M, P, U, V; IO-520-C, CB, E, M, MB IO-550-A, B, C, E; O-470-B, E, M, R, S, U; TSIO-470-B2, B3, C, D; TSIO-520-B, BB, D, DB, E, EB, J, JB, K, KB, L, LB, N, NB, U, UB, VB, WB; TSIOL-550-A
SA531608	1	Continental Engines: GO-300-A, C, D, E
SA532125	1	Continental Engines: O-470-2
SA532126	1	Continental Engines: O-470-2
SA532129	1	Continental Engines: O-470-2, 15, A, E, J; IO-470-J, K; E165-2; E185-1, 3, 8, 9, 11; IO-470-J, K; E225-4, 8; FSO-470-A
SA532200	102	Continental Engines: E-165 Series; E-185 Series; E-225 Series; O-470 Series; IO-470 Series; TSIO-470 Series
SA532432	77	Continental Engines: C125-2; C145-2; 2H; C75; C85; C90; GO-300-A, C, D, E; GTSIO-520-C, D, F, H, K, L, M, N; IO-360-A, A6, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D,
SA532509	76	Continental Engines: O-470-11
SA532518	76	Continental Engines: O-470-4, 13
SA532519	76	Continental Engines: O-470-4, 11, 13
SA532520	90	Continental Engines: O-470-4, 13



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA533355	76	Continental Engines: C75; C85; C90; IO-520-B, BA, BB, C, CB, MB; IO-550-G; O-200-A, B; TSIO-360-A, B, C, D, H, JB; TSIO-520-B, B10, B12, B2, BB, BB10, BB12, BE, D, DB, E, E10, E2, E4, E9, EB, EB10, J, J2, J4, JB, JB10, JB12, JB2, JB4, K, K2, KB, KB2, KB4
SA533399	1	Continental Engines: C-75; C-85; C-90; C-125; C-145; O-200; E-165; E-185; E-225; O-300-A, B, C, D; GO-300-A, C, D, E
SA534079	76	Continental Engines: O-470-4, 13
SA534316	76	Continental Engines: O-470-A, P
SA534610	90	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-346; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-A, B, C, D, E, F, G, L; LTSIO-520-AE; O-470-A, B, E, G, J, K, L, M, P, R, S,
SA534655	51	Continental Engines: IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, D, E, F, J, K, L; IO-550-C, D, E, F, L; O-470-A, B, E, G, J, K, L, M, P, R, S, U; TSIO-470-B1, B2, B3, C, D; TSIO-520-AE, AF, C, CE, G, H, M, P, R, T
SA534685	54	Continental Engines: IO-346; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-A, C, D, E, F, G, L; O-470-A, B, E, G, J, K, L, M, P, R, S, U; TSIO-470-B1, B2, B3, C, D; TSIO-520-AF, B, BB,
SA534715	77	Continental Engines: IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, D, E, F, J, K, L; IO-550-C, D, E, F, L; O-470-A, B, E, G, J, K, L, M, P, R, S, U; TSIO-470-B1, B2, B3, C, D; TSIO-520-AF, C, G, H, M, P, R
SA534740	76	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-346; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, J, K, L, M, MB; IO-550-A, B, C, D, E, F, G, L; LTSIO-520-AE; O-470-A, B, E, G, J, K, L, M, P, R, S, U;
SA534743	76	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, J, K, L, M, MB; IO-550-A, B, C, D, E, F, G, L; LTSIO-520-AE; O-470-A, B, E, G, J, K, L, M, P, R, S, U; TSIO-47
SA534750	76	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-346; IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-A, B, C, D, E, F, G,
SA534857	95	Continental Engines: IO-470-C, D, E, F, G, H, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-A, B, C, D, E, F, L; O-470-B, G, K, L, M, P, R, S, U; TSIO-470-B1, B2, B3, C, D; TSIO-520-AF, B, BB, C, CE, D, DB, E, EB, G,



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA534857-S	95	Continental Engines: IO-470-C, D, E, F, G, H, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-A, B, C, D, E, F, L; O-470-B, G, K, L, M, P, R, S, U; TSIO-470-B1, B2, B3, C, D; TSIO-520-AF, B, BB, C, CE, D, DB, E, EB, G.
SA534863	76	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-346; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-A, B, C, D, E, F, G, L; LTSIO-520-AE; O-470-A, B, E, G, J, K, L, M, P, R, S.
SA534895	4	Continental Engines: IO-470-J, K; O-470-A, E, J; E165-2; E185-1, 3, 8, 9, 11; E225-4, 8
SA534940	76	Continental Engines: GTSO-520-C, D, F, H, K, L, M, N; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, D, E, F, J, K, L; IO-550-D, E, F, L; LTSIO-520-AE; O-470-A, B, E, G, J, K, L, M, P, R, S, U; TSIO-470-B1, B2, B3, C, D; TSIO-520-AE, AF
SA534941	76	Continental Engines: GTSIO-520-C, D, F, H, K; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U; O-470-A, B, E, G, J, K, K5, L, M, P, R, S, U; TSIO-470-B1, B2, B3, C, D; TSIO-520-C, G, H
SA535008A	101	Continental Engines: IO-520-A, BA, BB, F, J, K, L; TSIO-520-AF, C, CE, D, G, H, M, P, R, T, UB; GTSIO 520-L, M, N; IO-470-C, E, F, G, H, J, K, N, R, S; O-470-A, G, J, K, L, P, R, S, U; IO-550-D, E, F, G, L; IO-346
SA535057	76	Continental Engines: E165-2; E185-1, 3, 8, 9, 11; E225-4, 8
SA535091-.62		Continental Engines: A65; A75; C125-2; C145-2, 2H; GO-300-A, C, D, E; GTSIO-520-C, D, F, H, K, L, M, N; IO-360-A, C, D, G, H, J, K, AB, CB, DB, GB, HB, JB, KB; IO-520-A, D, E, F, J, K, L; IO-550-D, E, F, L; LTSIO-360-E, KB; LTSIO-520-AE; O-300-A, B, C, D
SA535324	76	Continental Engines: A65; C125-2; C145-2H; C75, 85, 90; GO-300-A, C, D, E; O-200-A, B; O-300-A, B, C, D; E165-2; E185-1, 3, 8, 9, 11; E225-4, 8
SA535634	77	Continental Engines: GTSIO-520-L, M, N; IO-346; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, MB; IO-550-A, B, C, D, E, F, G, L; O-470-A, B, E, G, J, K, L, M, P, R, S, U; TSIO-470-B2, B3, C, D; TSIO-
SA535661	14	Continental Engines: IO-520-A, D, E, F, J, K, L; TSIO-470-B, C, D; TSIO-520-AF, C, CE, G, H, M, P, R, T; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; O-470-A, B, E, G, J, K, L, M, P, R, S, U; IO-550-D, E, F, L
SA535666	49	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-346; IO-520-A, C6, CB6, D, E, F, J, K, L; LTSIO 520-AE; O-470-B, E, G, L, M, P, R32; TSIO-470-B1, B2, B3, C, D; TSIO-520-AE, AF, C, CE, G, H, M, P, R, T; IO-470-C, D, E, F, G, H, J, K, L, M, N, P,



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA535668	102	Continental Engines: O-470-M; IO-470-D, L, U, V; TSIO-470-B, C, D; IO-520-A, Specs. 9, 12, 7, 22, 24, 30, 34; F Specs. 2, 9, 11, 13, 17; L Specs. 3, 7; TSIO-520-C, G, H, M, P, R
SA535823	102	Continental Engines: O-470-A, B, E, G, J, K, L, M, P, R, S, U; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, D, E, F, J, K, L; TSIO-520-C, G, H, M, P, R, T, AF, AE, CE; GTSIO-520-C, D, F, H, K, L, M, N
SA535885	76	Continental Engines: GTSIO-520-L, M, N; IO-470-D, L, M, P, U, V; IO-520-C, CB, E, M, MB; IO-550-A, B, C, E; O-470-B, E, M; TSIO-470-B2, B3, C, D; TSIO-520-B, BB, E, EB, J, JB, K, KB, L, LB, N, NB, VB, WB; TSIO-550-A
SA535933	77	Continental Engines: IO-470-C, D, E, F, M, P, S, U, V; IO-520-A, D, E, F, J, K, L; IO-550-D, F; O-470-A, B, E, G, J, K, L, M, R, S, U; TSIO-520-T
SA536033	1	Continental Engines: O-470; GIO-470; GSO-526; IO-470; IO-520; GSIO-520; FSO-526; FSO-470; TSIO-470; TSIO-520
SA536379	54	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-346; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, K, L, M, MB; IO-550-A, B, C, D, E, F, G, L; O-470-A, B, E, G, J, K, L, M, P, R, S, U; TSIO-470-B1,
SA536410	102	Continental Engines: IO-346-A; O-470-A, E, J; IO-470-J, K
SA536410	102	Continental Engines: IO-346-A; O-470-A, E, J; IO-470-J, K
SA536413	76	Continental Engines: IO-470-C, D, E, F, G, H, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-A, B, C, D, F, L; O-470-B, G, K, L, M, P, R, S, U; TSIO-470-B1, B2, B3, C, D; TSIO-520-AF, B, BB, C, CE, D, DB, E, EB, G, H,
SA536563	54	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-346; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-A, B, C, D, E, F, G, L; O-470-A, B, E, G, J, K, L, M, P, R, S, U; TSIO-470-B
SA536634	76	Continental Engines: O-470-4, 13; IO-346; E-165-2; E-185-1, 3, 8, 9, 11; E-225-4, 8
SA536740	90	Continental Engines: IO-346; E-165-2; E-185-1, 3, 8, 9, 11; E-225-4, 8



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA536799	76	Continental Engines: O-470-4, 13
SA536938	1	Continental Engines: O-470-A, B, E, J, K, L, M, N, P, R, 2, 4, 11, 13A; E-185-1, 3, 8, 9, 11; E-225-8; IO-470-J, K; GSO-470-A
SA537019	54	Continental Engines: GTSIO-C, D, F, H, K, L, M, N; IO-470-C, D, E, F, G, H, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-A, B, C, D, E, F, L; O-470-A, B, E, G, J, K, L, M, P, R, S, U; TSIO-470-B1, B2, B3, C, D; TSIO
SA537064	1	Continental Engines: IO-470-11
SA537282	76	Continental Engines: IO-470-D, F19, F23, F3, F4, F5, F7, L, M, S2, S8; IO-520-A, D, E, F, J, K, L; LTSIO-520-AE; O-470-B, J11, K17, L16, M, R14, R6; TSIO-470-B1; TSIO-520-AE
SA537296	54	Continental Engines: IO-346; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-A, B, C, D, E, F, L; O-470-A, B, E, G, J, K, L, M, P, R, S, U; TSIO-470-B1, B2, B3, C, D; TSIO-520-AF, B, BB,
SA537401	1	Continental Engines: O-470-A, E, J, K, L
SA537728	78	Continental Engines: IO-346; IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; IO-470-S; IO-520-A, F, J, K, L; LTSIO-360-E, EB, KB; TSIO-360-A, AB, B, C, C6, CB6, D, E, EB, F, FB, GB, H, HB, JB, KB, LB, MB; TSIO-520-AF, C, CE, G, H, M, P, R
SA537745	76	Continental Engines: GTSIO-520-C, D, F; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, D, E, F, J, K, L; IO-550-D, E, F, L; LTSIO-520-AE; O-470-A, B, E, G, J, K, L, M, P, R, S, U; TSIO-470-B1; TSIO-520-AE, AF, C, CE, G, H, M, P, R, T
SA537749	76	Continental Engines: IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, D, E, F, J, K, L; IO-550-D, E, F, L; O-470-A, B, E, G, J, K, L, M, P, R, S, U; TSIO-470-B1, B2, B3, C, D; TSIO-520-AF, C, G, H, M, P, R
SA537848	1	Continental Engines: O-470; IO-470
SA537870	97	Continental Engines: C75-8, 12, 14, 16, 8F, 12F, 14F, 16F; C85-8, 12, 14, 16, 8F, 12F, 14F, 16F; C90-8, 12, 14, 16, 8F, 12F, 14F, 16F; O-200-A, B; C125-2; C145-2, 2H; O-300-A, B, C, D; GO-300-A, C, D, E, F; A65, A75



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA538185	76	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, D, E, F, J, K, L; IO-550-D, F; O-470-A, B, E, G, J, K, L, M, P, R, S, U; TSIO-470-B1, B2, B3, C, D; TSIO-520-AF, C, G, H, M, P, R, T
SA538304	101	Continental Engines: IO-520-A, BA, BB, C, CB, D, E, F, J, K, L, M, MB; TSIO-470-B1, B2, B3, C, D; TSIO-520-AF, B, C, CE, D, E, G, H, J, K, L, M, N, P, R, T, UB, VB, WB; IO-470-C, D, E, F, G, H, L, M, N, P, R, S, U, V; O-470-B, G, K, L, M, P, R, S, U; IO-
SA538468	77	Continental Engines: IO-470-D, E, G, L, M, P, R, U, V; IO-520-C, CB, E; IO-550-C, E; O-470-B, E, M
SA538556	137	Continental Engines: C75, 85, 90; O-200-A, B
SA538684	1	Continental Engines: GO-300-A, C, D, E; IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; LTSIO-360-E, EB, KB; TSIO-360-A, AB, B, C, CB, D, DB, E, EB, F, FB, GB, H, HB, JB, KB, LB, MB
SA538804	76	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, D, E, F, J, K, L; IO-550-D, E, F, L; LTSIO-520-AE; O-470-A, B, E, G, J, K, L, M, P, R, S, U; TSIO-470-B1, B2, B3, C, D; TSIO-520-AE, A
SA538999	78	Continental Engines: C125-2; C145-2, 2H; C75; C85; C90; GO-300-A, C; GTSIO-520-C, D, F, H, K, L, M, N; IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, D, E, F, J, K, L; IO-550-D, E,
SA539058	78	Continental Engines: GO-300-D, E; GTSIO-520-C, D, F, H, K, L, M, N; IO-346; IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; IO-470-C, D, E, F, G, H, J, K, L, M, N, N3, P, R, S, U, V, V10; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-55
SA539467	1	Continental Engines: IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; O-470-A, B, E, G, J, K, L, M, P, R, S, U, 4, 13, 13A; TSIO-470-B1, B2, B3, C, D
SA539473	1	Continental Engines: O-470; IO-470; FSO-470; TSIO-470
SA539568	1	Continental Engines: IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, D, E, F, J, K, L; IO-550-D, E, F, L; O-470-B, E, G, J, K, L, M, P, R, S, U; TSIO-470-B1, B2, B3, C, D; TSIO-520-AF, C, G, H, M, P, R
SA539740	77	Continental Engines: IO-470-C, D, E, F, G, H, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; O-470-B, G, K, L, M, P, R, S, U; TSIO-470-B1, B2, B3, C, D; TSIO-520-AF, B, BB, C, D, DB, E, EB, G, H, J, JB, K, KB, L, LB, M, N, N



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA539800	1	Continental Engines: IO-346; IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E; IO-550-A, B, C, D, E, F, G, L; O-300-D; O-470-B, E, G, J, K, L, M, P, R, U; TSIO
SA539814	1	Continental Engines: O-470; IO-470
SA539840	90	Continental Engines: A65, A75; C125-2; C145-2, 2H; C75, C85, C90; GO-300-A, C, D, E; O-200-A, B; O-300-A, B, C, D
SA539942	54	Continental Engines: GTSIO-520-C, D, H, L, M, N; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO 520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-A, B, D, E, F, G, L; TSIO-470-B1, B2, B3, C, D; TSIO-520-AF, B, BB, C, CE, D, DB, E, EB, G
SA539988	54	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; LTSIO-520-AE; TSIO-470-B1, B2, B3, C, D; TSIO-520-AE, AF, B, BB, C, CE, D, DB, E, EB, G, H, J, JB, K, KB, L, LB, M, N, NB, P, R, T, U, UB, VB, WB;
SA539988V	147	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; LTSIO-520-AE; TSIO-470-B1, B2, B3, C, D; TSIO-520-AE, AF, B, BB, BE, C, CE, D, DB, E, EB, G, H, J, JB, K, KB, L, LB, M, N, NB, P, R, T, U, UB, VB,
SA5484	76	Continental Engines: C75; C85; C90; O-200-A, B
SA625065	1	Continental Engines: O-470; IO-470; TSIO-470
SA625142	49	Continental Engines: IO-346; IO-470-J, K; LTSIO-520-AE; O-470-A, E, J; TSIO-520-AE; E165-2; E185-1, 3, 8, 9, 11; E225-4, 8
SA625147	1	Continental Engines: LIO-470-A; IO-470-C, G, R, P; O-470-G, 15
SA625303	76	Continental Engines: IO-470-C, D, E, F, F5, G, H, J, L, M, N, R, S; IO-520-A, D, E, F, J, K, L; O-470-A, B, E, G, J, K, K14, L, M, P, R, S, U; LTSIO-520-AE; TSIO-470-B1; TSIO-520-AE
SA625393	54	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-346; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-A, B, C, D, E, F, G, L; LTSIO-520-AE; O-470-A, B, E, G, J, K, L, M, P, R, U,



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA625457	54	Continental Engines: GTSIO-520-C, D, H, L, M, N; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M; IO-550-B, C, D, E, F, L; TSIO-470-B1, B2, B3, C, D; TSIO-520-AF, B, BB, C, CE, E, EB, G, H, M, P, R,
SA625615	161	TCM Engines: O-470-B, G, K, L, M, P, R, S, U; IO-470-C, D, E, F, G, H, L, M, N, P, R, S, U, V; TSIO-470-B, C, D; IO-520-A, BA, C, D, E, F, J, K, L, M; TSIO-520-B, D, E, J, K, L, M, N, UB, VB, WB
SA625821	1	Continental Engines: E-185; E-225; O-470-A, E, J, G, K, L, N
SA625957	78	Continental Engines: GO-300-A, C, D, E; IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; LTSIO-360-E, EB, KB; TSIO-360-A, AB, B, C, CB, D, DB, E, EB, F, FB, GB, H, HB, JB, KB, LB, MB
SA625958	1	Continental Engines: C125-2; C145-2, 2H; C75; C-85; C-90; GO-300-A, C, D, E; IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; LTSIO-360-E, EB, KB; O-200-A, B; O-300-A, B, C, D; TSIO-360-A, AB, B, C, CB, D, DB, E, EB, F, FB, GB, H, HB, JB, KB, LB,
SA625961	97	Continental Engines: C75-8, 12, 14, 16, 8F, 12F, 14F, 16F; C85-8, 12, 14, 16, 8F, 12F, 14F, 16F; C90-8, 12, 14, 16, 8F, 12F, 14F, 16F; O-200-A, B; C125-2; C145-2, 2H; O-300-A, B, C, D; GO-300-A, C, D, E, F
SA625966	90	Continental Engines: IO-470-C, D, D12, D15, D19, D27, D30, D42, D44, D50, D52, E, F, F18, F26, G, H, J, K, K14, L, N, P, R, U, V; IO-520-A, A12, A9, D, D22, D24, D27, D30, D34, D4, D40, E, E2, E6, E7, F, F11, F13, F17, F2, F5, F6, F7, F9, J, K, L, L3, L7
SA626140	14	Continental Engines: GO-300-A, C, D, E; IO-346; IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; IO-470-C, D, E, F, H, J, K, L, M, N, P, R, S, U, V; LTSIO-360-E, EB, KB; O-470-4, 11, 15, A, B, E, G, J, K, L, M, P, R, S, U; TSIO-360-A, AB, B, C, CB
SA626341	76	Continental Engines: IO-470-D, D12, D15, D19, D27, D30, D42, D44, D50, D52, F18, F26, K, L, L11, L12, L15, L16, L19, L20, L21, L22, L5, L8, L9, U, V; IO-520-A12, A7, A9, D22, D24, D27, D30, D33, D34, D35, D4, D40, E2, E6, E7, F11, F13, F17, F2, F5, F6, F
SA626342	76	Continental Engines: IO-470-D, D12, D15, D19, D27, D30, D42, D44, D50, D52, F18, F26, K14, L, L11, L12, L15, L16, L19, L20, L21, L22, L5, L8, L9, U, V; IO-520-A12, A7, A9, D22, D24, D27, D30, D34, D4, D40, E2, E6, E7, F11, F13, F17, F2, F5, F6, F7, F9, L
SA626348	1	Continental Engines: GSO-526-A; GSIO-520-C, D; GIO-470-A; TSIO-470-B, C, D; TSIO-520-A, B, C, D, E
SA626487	102	Continental Engines: C-125-2; C-145-2, 2H; GO-300-A, C, D, E; IO-360-A, C, D, G, H, J, K; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, D, E, F, J, K, L; IO-550-D, E, F, L; LTSIO-360-E, KB; LTSIO-520-AE; O-300-A, B, C, D; O-470-A, B, E



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA626540	1	Continental Engines: O-470; IO-470; LIO-470; IO-346; IO-520; E-185, E-225
SA626543	90	Continental Engines: C125-2; C145-2, 2H; C75, C85, C90; GO-300-A, C, D, E; IO-360-A6; O-200-A, B; O-300-A, B, C, D
SA626564		Continental Engines: GO-300-A, C, D, E
SA626566	51	Continental Engines: GO-300-A, C, D, E
SA626740	14	Continental Engines: O-470-G, P; IO-470-C, D, E, F, G, H, J, K, L, M, N, R, S, U, V
SA626741	1	Continental Engines: O-470-G, P; IO-470-C, D, E, F, G, H, J, K, L, N, R, S, U, V
SA626813	54	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-346; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-A, B, C, D, E, F, G, L; TSIO-360-MB; TSIO-470-B1, B2, B3, C, D; TSIO-520-AF,
SA626879-1	137	Continental Engines: TSIO-520-C, G, H, M, P, R, T, AF, CE, D, UB, B, E; IO-520-A, BA, BB, C, CB, D, E, F, J, K, L, M; IO-470-C, H, J, D, E, G, P, R, F, K, N, L, M, S; IO-550-B, C; GTSIO-520-C, D, H
SA626889	54	Continental Engines: IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-A, B, C, D, E, F, G, L; O-470-G; TSIO-470-B1, B2, B3, C, D; TSIO-520-AE, AF, B, BB, BE, C, CE, D, DB, E, EB, G, H, J,
SA626983	76	Continental Engines: O-200-A, B
SA626992	27	Continental Engines: O-470-K, L, R
SA627246	1	Continental Engines: A65; A75; C-75; C-85; C-90; O-200



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA627330	1	Continental Engines: C-90; C-145; O-200; O-300; GO-300
SA627336	1	Continental Engines: C145-2, 2H; C-90-8F, 8FJ, 12F, 12FJ, 14F; O-200-A; O-300-A, B, C, D; GO-300-A, C, D, E
SA627368	76	Continental Engines: IO-470-D, E, G, L, M, P, R, U, V; IO-520-C, CB, E; IO-550-C, E
SA627429	90	Continental Engines: A65, A75; C125-2; C145-2, 2H; C75; C85; C90; IO-470-J, K; LTSIO-520-E; O-200-A, B; O-300-A, B, C, D; O-470-A, E, J; TSIO-520-AE; E165-2; E185-1, 3, 8, 9, 11; E225-4, 8, 11
SA627433	78	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, D, D11, D15, D2, E, F, J, K, L; IO-550-D, E, F, L; LTSIO-360-E, EB, KB; O-470-
SA627480	1	Continental Engines: IO-470-D, E, F, G, H, L, M, N, P, S, T, U, V; O-470-K, L, R; TSIO-470-B, C, D; GIO-470-A
SA627496	77	Continental Engines: GO-300-A, C, D, E; GTSIO-520-C, D, F, H, K, L, M, N; IO-360-A, C, D, G, H, J, K; IO-470-D, L, U, V; IO-520-B, BA, BB, C, CB, M, MB; IO-550-A, B, C, D, E, F, G; LTSIO-360-E, KB; LTSIO-520-AE2, AE3; O-470-M; TSIO-360-A, B, C, D, E, F,
SA627693	78	Continental Engines: IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; LTSIO-360-E, EB, KB; TSIO-360-A, AB, B, C, CB, D, DB, E, EB, F, FB, GB, H, HB, JB, KB, LB, MB
SA627722	1	Continental Engines: IO-346; IO-520; GSIO-520; TSIO-520
SA627731	78	Continental Engines: IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; LTSIO-360-E, EB, KB; TSIO-360-A, AB, B, C, CB, D, DB, E, EB, F, FB, GB, H, HB, JB, KB, LB, MB
SA627738	1	Continental Engines: IO-470
SA627795	1	Continental Engines: O-470-G, P; IO-470-C, D, E, F, G, H, J, K, L, M, N, R, S, U, V



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA627993	76	Continental Engines: GO-300-D, E; IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; LTSIO-360-E, EB, KB; O-300-D; TSIO-360-A, AB, B, C, CB, D, DB, E, F, FB, G, GB, H, HB, JB, KB, LB, MB
SA628109	54	Continental Engines: IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; O-470-A, B, E, G, J, K, L, M, P, R, S, U; TSIO-520-AF, B, BB, BE, C, D, DB, E, EB, G, H, J, JB, K, KB, L, LB, M, N, NB, P, R,
SA628136	1	Continental Engines: TSIO-470
SA628260	54	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; TSIO-470-B1, B2, B3, C, D; TSIO-520-AF, B, BB, BE, C, CE, D, DB, E, EB, G, H, J, JB, K, KB, L, LB, M, N, NB, P, R, T, U, UB, VB, WB; O-470-B, G, K
SA628309	1	Continental Engines: C125-2; C145-2, 2H; C75; C85; C90; GO-300-A, C, D, E; O-200-A, B; O-300-A, B, C, D
SA628321	54	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-D, F, L, M, MB; IO-550-A, B, C, D, F, G, L; LTSIO-360-E, EB, KB; O-470-A, B, E, G,
SA628488	54	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-550-G; O-470-A, B, E, G, J, K, L, M, P, R, S, U; TSIO-470-B1, B2, B3, C, D; TSIO-520-AE, AF, B, C, CE, D, E, G, H, J, K, L, M, N, P, R, T, U,
SA628555-1	137	Continental Engines: TSIO-520-B, E, D
SA628555-16		Continental Engines: O-200-A, B
SA628555-3	137	Continental Engines: GTSIO-520-F, K; TSIO-520-K, J, N
SA628556	54	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-550-G; LTSIO-360-E, KB; LTSIO-520-AE; TSIO-360-A, B, C, D, E, F, GB, H, JB, KB, LB, MB; TSIO-470-B1, B2, B3, C, D; TSIO-520-AE, AF, B, BB, BE, C, CE, D, DB, EB, G, H, JB, K, KB, L, LB, M, N, NB, P
SA628572	76	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; TSIO-470-B1, B2; TSIO-520-B, BB, D, DB, E, EB, J, JB, K, KB, L, LB, N, NB, UB, VB, WB; TSIOL-550-A



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA628750	1	Continental Engines: O-470; TSIO-520; IO-470; IO-520; TSIO-470; IO-360
SA628754	1	Continental Engines: O-470; IO-470
SA628939	1 & 16	Continental Engines: O-300; C-145; O-470
SA628940	1	Continental Engines: O-300; O-200; GO-300; C-90; C-145
SA628975	48	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N
SA628978	14	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; GIO-470
SA628985	1	Continental Engines: IO-470-D, E, F, G, L, M; TSIO-470-B
SA629016	76	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N
SA629077	54	Continental Engines: GTSIO-520-C; IO-346; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-A, B, C, D, E, F, G, L; LTSIO-520-AE; O-470-A, B, E, G, J, K, L, M, P, R, S, U; TSIO-470-B1, B2,
SA629104	54	Continental Engines: IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-A, B, C, D, E, F, G, L; O-470-A, B, E, G, J, K, L, M, P, R, S, U; TSIO-470-B1, B2, B3, C, D; TSIO-520-AE, AF, B, BB, B
SA629116	76	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N
SA629117	54	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-346; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-A, B, C, G; LTSIO-520-AE; TSIO-470-B1, B2, B3, C, D; TSIO-520-AE, AF, B, BB,



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA629159	76	Continental Engines: GTSIO-520-C; TSIO-470-B1, B2, B3, C, D
SA629196	137	Continental Engines: IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; TSIO-360-E, F, GB, KB, LB, MB, EB, FB; LTSIO-360-E, EB, KB
SA629202	76	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-346; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-A, B, C, D, E, F, G, L; LTSIO-520-AE; O-470-A, B, E, G, J, K, L, M, R, S, U;
SA629340	54	Continental Engines: IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; O-470-A, B, E, G, J, K, L, M, P, R, S, U; TSIO-520-AF, B, BB, BE, C, D, DB, E, EB, G, H, J, JB, K, KB, L, LB, M, N, NB, P, R,
SA629401	1	Continental Engines: IO-346-A, B; IO-520-A, B, C, D, E, F; TSIO-520-A, B, C, D, E; GTSIO-520-C
SA629404	1	Continental Engines: C125-2; C145-2, 2H; C75; C85; C90; O-300-A, B, C, D; O-200-A, B
SA629436	76	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-346; IO-520-B, BA, BB, C, CB, M, MB; IO-550-A, B, C, G; TSIO-520-B, BB, BE, D, DB, E, EB, J, JB, K, KB, L, LB, N, NB, UB, VB, WB; TSIOL-550-A
SA629609	14	Continental Engines: O-300-A
SA629690	45	Continental Engines: IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; LTSIO-360-E, EB, KB; TSIO-360-A, AB, B, C, CB, D, DB, E, F, FB, GB, H, HB, JB, KB, LB, MB
SA629702	78	Continental Engines: IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; LTSIO-360-E, EB, KB; TSIO-360-A, AB, B, C, CB, D, DB, E, EB, F, FB, GB, H, HB, JB, KB, LB, MB
SA629706	14	Continental Engines: IO-360-A, C, D; TSIO-360-A, B
SA629707	14	Continental Engines: GO-300-A, C, D, E



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA629711		Continental Engines: IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; LTSIO-360-E, EB, KB; TSIO-360-A, AB, B, C, CB, D, DB, E, EB, F, FB, GB, H, HB, JB, KB, LB, MB
SA629747		Continental Engines: IO-520-B, BA, BB, C, CB, M, MB; IO-550-A, B, C, G; TSIO-520-B, BB, BE, D, DB, E, EB, J, JB, K, KB, L, LB, N, NB, U, UB, VB, WB; TSIOL-550-A
SA629848	1	Continental Engines: IO-470
SA629891	1	Continental Engines: GIO-470; GSIO-520; IO-346; IO-520; TSIO-520
SA629925	76	Continental Engines: IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; LTSIO-360-E, EB, KB; TSIO-360-A, AB, B, C, CB, D, DB, E, F, FB, G, GB, H, HB, JB, KB, LB, MB
SA630046	1	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-346; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-A, B, C, D, E, F, G, L; TSIO-520-B, BB, C, D, DB, E, EB, G, H, J, JB, K, KB, L, LB, M, N, NB, P, R, T, UB, VB, WB; TSIO-520-BE, CE;
SA630046-1	101	Continental Engines: IO-520-A, BA, BB, C, CB, D, E, F, J, K, L, M, MB; TSIO-520-B, C, D, E, G, H, J, K, L, M, N, P, R, T, UB, VB, WB; GTSIO-520-C, D, F, H, K, L, M, N; IO-550-A, B, C, D, E, F, G, L; IO-346
SA630261	14	Continental Engines: GO-300-A, C, D, E; GIO-300; C145-2, 2H; O-300-A, B, C, D; IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; GTSIO-520-C, D, F, H, K, L, M, N; O-470-A, B, E, G, J, K, L, M, P, R, S, U; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K,
SA630262	1	Continental Engines: IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; TSIO-360-AB, CB, DB, FB, HB; LTSIO-360-EB
SA630286	76 & 137	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; IO-550-G; LTSIO-360-E, EB, KB; LTSIO-520-AE; TSIO-360-A, AB, C, D, DB, E, EB, F, FB, GB, H, HB, JB, KB, LB, MB; TSIO-520-AE, BE
SA630350	76	Continental Engines: IO-470-S; IO-520-A, F, J, K, L; IO-550-F, L; TSIO-520-AF, C, CE, G, H, M, P, R
SA630365	78	Continental Engines: IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; LTSIO-360-E, EB, KB; TSIO-360-A, AB, B, C, CB, D, DB, E, EB, F, FB, GB, GB4, H, HB, JB, KB, LB



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA630464	1	Continental Engines: IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U V; TSIO-470-B1, B2, B3, D; TSIO 520-AE, C, G, H, M, P, R, T; IO-520-A, D, E, F, J, K, L; O-470-A, E, G, J, K, L, P, R; GTSIO-520-C, D, F, H, K, L, M, N
SA630591	1	Continental Engines: IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; O-470-A, B, E, G, J, K, L, M, P, R, S, U; TSIO-470-B1, B2, B3, C, D; TSIO-520-B, BB, C, D, DB, E, EB, G, H, J, JB, K, KB, L,
SA630678	78	Continental Engines: IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; LTSIO-360-E, EB, KB; TSIO 360-A, AB, B, C, CB, D, DB, E, EB, F, FB, GB, H, HB, JB, KB, LB, MB
SA630680	54	Continental Engines: IO-346; IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; IO-520-B, BA, BB, C, CB, M, MB; IO-550-A, B, C, G; LTSIO-360-E, EB, KB; O-300-D; TSIO-360-A, AB, B, C, CB, D, DB, E, EB, F, FB, G, GB, H, HB, JB, KB, LB, MB; TSIO-520-B,
SA630681	54	Continental Engines: IO-346; IO-520-B, BA, BB, C, CB, M, MB; IO-550-A, B, C, G; TSIO-520-B, BB, BE, D, DB, E, EB, J, JB, K, KB, L, LB, N, NB, U, UB, VB, WB; TSIOL-550-A
SA630692		Continental Engines: IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; LTSIO-360-E, EB, KB; TSIO 360-A, AA, B, C, CB, D, DB, E, EB, F, FB, GB, H, HB, JB, KB, LB, MB
SA630693	54	Continental Engines: O-470-S, U; IO-520-BA, C, M; TSIO-520-B, C, E, H, J, K, L, M, N, P, R, T, U, VB, WB
SA630717	14	Continental Engines: IO-360-A, C, D
SA630742	78	Continental Engines: IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; LTSIO-360-E, EB, KB; TSIO 360-A, AB, B, C, CB, D, DB, E, EB, F, FB, GB, H, HB, JB, KB, LB, MB
SA630752	1	Continental Engines: IO-346-A, B; TSIO-520-A, B, C, D, E; GSIO-520-C; IO-520-A, B, C, D, E, F
SA630753	1	Continental Engines: IO-346-A, B; TSIO-520-A, B, C, D, E; GSIO-520-C; IO-520-A, B, C, D, E, F
SA630763	76	Continental Engines: IO-346; IO-520-B, BA, C, M, MB; TSIO-520-B, D, E, J, K, L, N



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA630789	1	Continental Engines: IO-520
SA630817	90	Continental Engines: GTSIO-520-C
SA630817-1	90	Continental Engines: TSIO-520-K
SA630824	76	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-550-G; TSIO-520-BE
SA630826	24	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-470-C, D, E, F, G, H, J, K, L, M, N, S, U, V; IC 520-A, B, BA, C, D, E, F, J, K, L, M; O-470-A, B, E, G, J, K, L, M, P, R, S, U; TSIO-520-AE, AF, B, C, D, E, G, H, J, K, L, M, N, P, R, T
SA630849	76	Continental Engines: IO-520-B, BA, BB, M, MB; TSIO-520-B, BB, BE, E, EB, J, JB, K, KB, L, LB, N, NB, VB, WB
SA630892	76	Continental Engines: IO-346; IO-520-B, BA, BB, C, CB, M, MB; IO-550-A, B, C, G; TSIO-520-B, BB, BE, D, DB, E, EB, J, JB, K, KB, L, LB, N, NB, UB, V, VB, WB; TSIOL-550-A
SA630895	101	Continental Engines: IO-520-BA, BB, C, CB, M, MB; IO-550-A, C, G; IO-346
SA630899	54	Continental Engines: IO-346; IO-520-B, BA, BB, C, CB, M, MB; IO-550-A, B, C, G; TSIO-520-B, BB, BE, D, DB, E, EB, J, JB, K, KB, L, LB, N, NB, U, UB, VB, WB; TSIOL-550-A
SA630916	76	Continental Engines: IO-346; IO-520-BA, C, M
SA630966	54	Continental Engines: O-200; TSIO-360-F; IO-520-C, M, BA; TSIO-520-B, D, E, J, K, L, N, T, U, VB, WB; GTSIO-520-F, K
SA630979-9	137	Continental Engines: TSIO-360-MB, E, F, KB, GB, LB, B, C, D, H, JB, AB, CB, DB, EB, FB, HB, A; LTSIO 360-E, EB, KB; TSIO-520-D, B, E, BB, EB, DB, J, JB, N, NB, K, KB, L, LB, WB, UB, VB, C, G, H, M, P, R, T, AE, CE; GTSIO-520-C



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA630993	137	Continental Engines: GTSIO-520-C
SA630993-1	137	Continental Engines: GTSIO-520-D, F, H, K, L, M, N
SA631034	76	Continental Engines: IO-346; IO-520-B, BA, BB, C, CB, M, MB; TSIO-520-B, BB, BE, D, DB, E, EB, J, JB, K, KB, L, LB, N, NB, UB, VB, WB; TSIOL-550-A; IO-550-B, C
SA631059	76	Continental Engines: IO-520-B, BA, BB, M, MB; IO-550-A, B, G; TSIO-520-B, BB, BE, D, DB, E, EB, J, JB, K, KB, L, LB, N, NB, UB, VB, WB; TSIOL-550-A
SA631088	49	Continental Engines: IO-346; IO-520-BA, C, M; IO-550-A, B, C, G; TSIO-520-B, BB, BE, D, DB, E, EB, J, JB, K, KB, L, LB, N, NB, U, UB, VB, WB; TSIOL-550-A
SA631250	1	Continental Engines: GTSIO-520-C
SA631263	54	Continental Engines: IO-346; IO-520-B, BA, BB, C, CB, M, MB; IO-550-A, B, C; TSIO-520-B, BB, D, DB, E, EB, J, JB, K, KB, L, LB, N, NB, U, UB, VB, W, WB; TSIOL-550-A
SA631475	1	Continental Engines: IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB
SA631481	1	Continental Engines: IO-470; GIO-470; TSIO-470
SA631496	31	Continental Engines: TSIO-470-B1, B2, B3, C, D; E165-2; E185-1, 3, 8, 9, 11; E225-4, 8; IO-346-A; O-470 A, B, E, G, J, K, L, M, P, R, S, U; IO-520-A, BA, C, D, E, F, J, K, L, M, BB, CB, MB; TSIO-520-AF, AE, B, BB, C, CE, D, DB, E, EB, G, H, J, JB, K, KB,
SA631501	1	Continental Engines: IO-470-D, E, F, H, L, M, N, S, T, U, V; TSIO-470-B, C, D; GIO-470-A
SA631520	54	Continental Engines: IO-520-M, BA; TSIO-520-B, D, K, L, M, N, P, R, T, U, VB, WB



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA631521	54	Continental Engines: IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-A, B, C, D, E, F, G, L; LTSIO-520-AE; O-470-A, B, E, G, J, K, L, M, P, R, S, U; TSIO-520-AE, AF, B, BB, BE, C, CE, D,
SA631544	90	Continental Engines: IO-470-C, D, E, F, R, S, U, V; O-470-B, G, K, L, M, P, R, S, U
SA631554		Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N
SA631654	78	Continental Engines: IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; LTSIO-360-E, EB, KB; TSIO-360-A, AB, B, C, CB, D, DB, E, EB, F, FB, GB, H, HB, JB, KB, LB, MB
SA631685	76	Continental Engines: GTSIO-520-L, M, N; IO-470-V; IO-520-A, D, E, F, J, K, L; LTSIO-520-AE; TSIO-520-AE, AF, CE, M, P, R, T
SA631727	1	Continental Engines: TSIO-470; GIO-470; IO-470
SA631729	1	Continental Engines: IO-520; GSIO-520; TSIO-520
SA631730	1	Continental Engines: GTSIO-520; IO-520; TSIO-520
SA631731	1	Continental Engines: IO-520
SA631794	36	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N
SA631808	91	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N
SA631815	24	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; TSIO-520-BE



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA631845	95	Continental Engines: IO-470-U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-A, B, C, D, E, F, G, L; O-470-U; TSIO-520-AF, B, BB, BE, C, CE, D, DB, E, EB, G, H, J, JB, K, KB, L, LB, M, N, NB, P, R, T, UB, VB, WB; TSIOL-550-A
SA631928	137	Continental Engines: IO-360-D19, D20, D25, D30, D31, D32, D34, DB19, DB20, DB25, DB30, DB31, DB32, HB, J, JB, K, KB; TSIO-360-GB, LB, MB; IO-520-A, D, E, F, J, K, L; IO-470-F23, F26, F7, S; O-470-R, S, U; IO-550-D, E, F, L; LTSIO-520-AE; TSIO-520-AE, AF,
SA631991	39	Continental Engines: IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; LTSIO-360-E, EB, KB; TSIO-360-A, AB, B, C, CB, D, DB, E, F, FB, GB, H, HB, JB, KB, LB, MB
SA632039	1	Continental Engines: IO-470-D, E, F, L, M, N, V; TSIO-470-B, C, D
SA632050	97	Continental Engines: O-200-A, B; IO-360-A, C, D, G, H, J, K, A5, A6, C5, C6, C7, D6, D7, D8, D9, D11, D12, D15, D19, D20, D21, D22, D23, D25, D26, D30, D31, D32, D33, D34, G2, H2, H3, H4, H5, H6, H7, J2, J3, J4, J5, K2, K3, K4; TSIO-360-A, B, A3
SA632085	102	Continental Engines: A65; C75; C85; C90; IO-346; IO-470-C, E, F, G, H, J, K, N, R, S; IO-520-A, B, BA, BB, D, F, J, K, L; IO-550-D, F, G, L; O-470-A, G, P, R, S; TSIO-520-AF, C, CE, D, DB, G, H, M, P, R, T, UB
SA632092-4	54	Continental Engines: IO-520-B, BA, BB, C, CB, M, MB; IO-550-A, B, C, G; TSIO-520-B, BB, BE, D, DB, E, EB, J, JB, K, KB, L, LB, N, NB, U, UB, VB, WB; TSIOL-550-A
SA632120A	98	Continental Engines: IO-346-A; IO-520-C, M, CB, MB; IO-550-A, B, C, G; TSIO-520-B, D, E, J, K, L, N, BB, DB, EB, JB, KB, LB, NB, UB, VB, WB; TSIOL-550-A; GTSIO-520-C, D, F, H, K, L, M, N
SA632141	78	Continental Engines: IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; LTSIO-360-E, EB, KB; TSIO-360-A, AB, B, C, CB, D, DB, E, EB, F, FB, GB, H, HB, JB, KB, LB, MB
SA632156	14	Continental Engines: IO-360-A, C, D; TSIO-360-A, B
SA632157	14	Continental Engines: IO-360-A, C, D; TSIO-360-A, B
SA632248	78	Continental Engines: IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; IO-550-G; LTSIO-360-E, EB, KB; TSIO-360-A, AB, B, C, CB, D, DB, E, EB, F, FB, GB, H, HB, JB, KB, LB, MB; TSIO-520-BE



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA632266	76	Continental Engines: IO-346; IO-520-B, BA, BB, C, CB, M, MB; IO-550-A, B, C, G; TSIO-520-B, BB, BE, D, DB, E, EB, J, JB, K, KB, L, LB, N, NB, UB, VB, WB; TSIOL-550-A
SA632310	76	Continental Engines: IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; LTSIO-360-E, EB, KB; TSIO 360-A, AB, B, C, CB, D, DB, E, F, FB, G, GB, H, HB, JB, KB, LB, MB
SA632310-S		Continental Engines: IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; LTSIO-360-E, EB, KB; TSIO 360-A, AB, B, C, CB, D, DB, E, F, FB, G, GB, H, HB, JB, KB, LB, MB
SA632372	76	Continental Engines: IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; IO-470-C, E, G, H, J, K, N, R, S; LTSIO-360-E, EB, KB; O-470-G, K14, L, P, R, S, U; TSIO-360-A, AB, B, C, CB, D, DB, E, FB, G, GB, H, HB, JB, KB, LB, MB
SA632443A-4	96	Continental Engines: TSIO-470-B, C, D; TSIO-520-B, D, E, J, K, L, N, UB, VB, WB, BB, DB, EB, JB, KB, LB, NB, C, G, H, M, P, R, T, AF, AE, CE; LTSIO-520-AE; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-B, BA, BB, C, CB, M, MB, A, D, E, F,
SA632443A-6	96	Continental Engines: IO-520-B, BA, BB, C, CB, M, MB; IO-550-A, B, C, G; TSIOL-550-A; TSIO-520-B, BB, D, DB, E, EB, J, JB, K, KB, L, LB, N, NB, UB, VB, WB
SA632459	76	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-550-G; TSIO-520-BE
SA632459-S		Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-550-G; TSIO-520-BE
SA632585	1	Continental Engines: TSIO-520
SA632655	76	Continental Engines: IO-346
SA632710	76	Continental Engines: GTSIO-520-D, H; TSIO-520-B, BB, CE, D, DB, E, EB, J, JB, K, KB, N, NB, U, UB, VB
SA632837	90	Continental Engines: A65, A75; C75, C85, C90; C125-2; C145-2, 2H; IO-346; IO-470-J, K; O-200-A, B; O-470-A, E, J; O-300-A, B, C, D



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA632857	14	Continental Engines: IO-360-C, D
SA632885	14	Continental Engines: IO-360-C, D
SA632892	95	Continental Engines: IO-346; IO-520-B, BA, BB, C, CB, M, MB; IO-550-A, B, C, G; TSIO-520-B, BB, BE, D, DB, E, EB, J, JB, K, KB, L, LB, N, NB, UB, VB, WB; TSIOL-550-A
SA632893	95	Continental Engines: IO-346; IO-520-B, BA, BB, C, CB, M, MB; IO-550-A, B, C, G; TSIO-520-B, BB, BE, D, DB, E, EB, J, JB, K, KB, L, LB, N, NB, UB, VB, WB; TSIOL-550-A
SA632932	52	Continental Engines: O-470-K, L, R
SA632945	76	Continental Engines: LTSIO-360-E, EB, KB; TSIO-360-A, AB, B, C, CB, D, DB, E, F, FB, G, GB, H, HB, JB, KB, LB, MB; IO-360-A, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB
SA633106	78	Continental Engines: IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; LTSIO-360-E, EB, KB; TSIO-360-A, AB, B, C, CB, D, DB, E, EB, F, FB, G, GB, H, HB, JB, KB, LB, MB
SA633136	48	Continental Engines: O-470-A, B, E, J, K, L, M, R, S, U
SA633141	1	Continental Engines: A65, A75; C75; C85; C90; O-200-A, B
SA633240	76	Continental Engines: C75; C85; C90; IO-520-B, BA, BB, C, CB, M, MB; O-200-A, B; TSIO-520-B, B10, B12, B2, BB, BB10, BB12, D, DB, E, E10, E2, E4, E9, EB, EB10, J, J2, J4, JB, JB10, JB12, JB2, JB4, K, K2, KB, KB2, KB4, L, LB, N, N10, N12, N14, N16, N2, N4,
SA633317	1	Continental Engines: O-470-K, L, R
SA633358	78	Continental Engines: LTSIO-360-E, EB, KB; TSIO-360-E, EB, F, FB, GB, GB4, KB, LB; TSIO-520-T



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA633398	1	Continental Engines: A65, A75; C75, C85, C90; O-200-A, B
SA633399	1	Continental Engines: A-65; C-85; C-90
SA633542	78	Continental Engines: LTSIO-360-E, EB, KB; TSIO-360-B, C, CB, E, EB, F, FB, GB, H, HB, JB, KB, LB, MB
SA633602	78	Continental Engines: C125-2; C145-2, 2H; IO-360-A, AB, B, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB LTSIO-360-E, EB, KB; O-300-A, B, C, D; TSIO-360-A, AB, B, C, CB, D, DB, E, EB, F, FB, GB, H, HB, J, JB, K, KB, LB, MB
SA633610	78	Continental Engines: C125-2; C145-2, 2H; IO-360-A, AB, B, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB LTSIO-360-E, EB, KB; O-300-A, B, C, D; TSIO-360-A, AB, B, C, CB, D, DB, E, EB, F, FB, GB, H, HB, J, JB, K, KB, LB, MB
SA633611	78	Continental Engines: C125-2; C145-2, 2H; IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; LTSIO 360-E, EB, KB; O-300-A, B, C, D; TSIO-360-A, AB, B, C, CB, D, DB, E, EB, F, FB, GB, H, HB, J, JB, K, KB, LB, MB
SA633752	76	Continental Engines: IO-360-C, CB, G, GB; TSIO-360-A, AB, D, DB, LB
SA633834	1	Continental Engines: GTSIO-520-D
SA633845	78	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-346; IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-A, B, C, D, E, F, G,
SA633958-3	54	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; LTSIO-360-E, EB, KB; LTSIO-520-AE; TSIO-360 A, AB, B, C, CB, D, DB, E, F, FB, G, GB, H, HB, JB, KB, LB, MB; TSIO-470-B1, B2, B3, C, D; TSIO-520-AE, AF, B, BB, BE, C, CE, D, DB, E, EB, G, H, J, JB, K,
SA633958-5	78	Continental Engines: GTSIO-520-C, D, H, L, M, N; LTSIO-360-E, EB KB; TSIO-360-A, AB, B, C, CB, D, DB, E, EB, F, FB, G, GB, H, HB, JB, KB, LB, MB; TSIO-520-AF, B, BB, C, D, DB, E, EB, G, H, L, LB, M, P, R, UB, WB
SA633976	78	Continental Engines: GO-300-A, C, D, E; IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; LTSIO-360-E, EB, KB; TSIO-360-A, AB, B, C, CB, D, DB, E, EB, F, FB, GB, H, HB, JB, KB, LB, MB



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA634033	14	Continental Engines: IO-520-A, B, C, D, E, F; TSIO-520-B, C, D; GTSIO-520-C
SA634503	54	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-520-BB, CB, MB; IO-550-A, B, C, D, E, F, G, L; TSIO-520-BB, BE, CE, DB, EB, JB, KB, LB, NB, UB, VB, WB; TSIOL-550-A
SA634505	54	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-A, B, C, G; LTSIO-520-AE; O-470-A, B, E, G, J, K, L, M, P, R, S, U; TSIO-520-AE, AF,
SA634511	77	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, D10, D15, E, F, J, K, L, M, MB; IO-550-D, E, F, L; O-470-A, B, E, G, J, K, L, M, P, R, S, U; TSIO-520-AE, AF, B,
SA634703	1	Continental Engines: IO-470; TSIO-470
SA635134	76	Continental Engines: TSIO-470-B1, B2, B3, C, D; IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, JB, K, KB; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, D, E, F, J, K, L; TSIO-520-AF, C, G, H, M, P, R, T; O-470-A, B, E, G, J, K, L, M, P, R,
SA635439	1	Continental Engines: IO-520-B, C; TSIO-520-B, D, E
SA635557	1	Continental Engines: O-470-K, L, R, B, M, P
SA635623	54	Continental Engines: IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; TSIO-470-B1, B2, B3, C, D; TSIO-520-AF, B, BB, C, D, DB, E, EB, G, H, J, JB, K, KB, L, LB, M, N, NB, P, R, T, U, UB, VB, WB; E165-2; E185-1, 3, 8, 9, 11; E225-4, 8; O-470-A, B, E,
SA635720	5	Continental Engines: GTSIO-520-C, D; TSIO-520-A, B, C, D, E; TSIO-470-B, C, D
SA635959	78	Continental Engines: IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; LTSIO-360-E, EB, KB; TSIO-360-A, AB, B, C, CB, D, DB, E, EB, F, FB, G, GB, H, HB, JB, KB, LB, MB
SA636242	31	Continental Engines: E165-2; E185-1, 3, 8, 9, 11; E225-4, 8; IO-346; O-470-A, B, E, G, J, K, L, M, P, R, S, U; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; TSIO-470-B, C, D; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; TSIO-520-C, G, H,



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA636465	90	Continental Engines: TSIO-360-MB; TSIO-520-B, BB, BE, E, EB, T, UB, VB
SA636931	78	Continental Engines: IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; LTSIO-360-E, EB, KB; TSIO-360-A, AB, B, C, CB, D, DB, E, EB, F, FB, G, GB, H, HB, JB, KB, LB, MB
SA637083	97	Continental Engines: C75-8, 12, 14, 16, 8F, 12F, 14F, 16F; C85-8, 12, 14, 16, 8F, 12F, 14F, 16F; C90-8, 12, 14, 16, 8F, 12F, 14F, 16F; O-200-A, B; C125-2; C145-2, 2H; O-300-A, B, C, D; GO-300-A, C, D, E, F; E165-2; E185-1, 3, 8, 9, 11; E225-4, 8
SA637268	138	Continental Engines: A-65; C-75; C-85; C-90; E-165-2; E-185-1, 3, 8, 9, 11; E-225-4-8; C-125-2; C-145-2, 2H; O-200-A, B; O-300-A, B, C, D; GO-300-A, C, D, E
SA637269	14	Continental Engines: C75; C85; C90; O-200; E-165; E-185; E-225; C-125; C-145; O-300-A, B, C, D; GO-300-A, C, D, E
SA637277-2	137	Continental Engines: GTSIO-520-F, K
SA637579	54	Continental Engines: IO-360-A, C, D, G, H, J, K, AB, CB, DB, GB, HB, JB, KB; TSIO-360-A, B, C, D, E, F, G, H, AB, CB, DB, EB, FB, GB, HB, JB, KB; LTSIO-360-E, EB, KB; IO-520-A, BA, C, D, E, F, J, K, L, M, BB, CB, MB; TSIO-520-B, C, D, E, G, H, J, K, L, M
SA637836	14	Continental Engines: GTSIO-520-C, D, F, G, H
SA637837	14	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-550-A, B, C, D, E, F, G, L; LTSIO-520-AE; O-470-A, B, E, G, J, K, L, M, P, R, S, U; TSIO-520-AE, AF, B, BB, BE, C, CE, D, DB, E, EB, G, H, J,
SA638172	78	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-360-A, C, D, G, H, J, K; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-A, B, C, D, E, F, G, L; LTSIO-360-E, EB, KB; LTSIO-520-A
SA639193	54	Continental Engines: IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-A, B, C, D, E, F, G, L; O-470-A, B, E, G, J, K, L, M, P, R, S, U; TSIO-470-B1, B2, B3, C, D; TSIO-520-AE, AF, B, BB, B
SA639198	51	Continental Engines: IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; LTSIO-360-E, EB, KB; TSIO-360-A, AB, B, C, CB, D, DB, E, EB, F, FB, G, GB, H, HB, JB, KB, LB, MB



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA639204	14	Continental Engines: O-470-B
SA639207	76	Continental Engines: TSIO-360-C, D, LB, MB
SA639282	47	Continental Engines: IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; TSIO-360-A, AB, B, C, CB, D, DB, E, EB, F, FB, G, GB, H, HB, JB, KB, LB, MB; LTSIO-360-E, EB, KB
SA639292	54	Continental Engines: C125-2; C145-2, 2H; C75; C85; C90; GO-300-A, C, D, E; IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; LTSIO-360-E, EB, KB; O-200-A, B; O-300-A, B, C, D; O-470-A, B, E, G,
SA639565	14	Continental Engines: IO-470-D, E, F, H, L, M, N, S, U, V; TSIO-470-B, C, D
SA639569	16 & 14	Continental Engines: O-470-G; IO-470-C, G, P, R, T; LIO-470-A
SA639570	51	Continental Engines: IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; LTSIO-360-E, EB, KB; TSIO-360-A, AB, B, C, CB, D, DB, E, F, G, GB, H, JB, KB, LB, MB
SA639573	54	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-470-C, D, E, F, G, H, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-A, B, C, D, E, F, G, L; O-470-B, G, K, L, M, P, R, S, U; TSIO-470-B1, B2, B3, C, D; TSIO-5
SA639577	14	Continental Engines: IO-520-A, B, C, D, E, F, J, K, L; TSIO-520-B, C, D, E, G, H, J, K; GTSIO-520-C, D, F, G, H
SA639579	51	Continental Engines: IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; LTSIO-360-E, EB, KB; TSIO-360-A, AB, B, C, CB, D, DB, E, F, FB, G, GB, H, HB, JB, KB, LB, MB
SA639580	51	Continental Engines: IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; LTSIO-360-E, EB, KB; TSIO-360-A, AB, B, C, CB, D, DB, E, EB, F, FB, G, GB, H, HB, JB, KB, LB, MB
SA639629	54	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-470-C, D, E, F, G, H, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-A, B, C, G; O-470-B, G, K, L, M, P, R, S, U; TSIO-470-B1, B2, B3, C, D; TSIO-520-AF, B, BB



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA639640	31	Continental Engines: C125-2; C145-2, 2H; C75, 85, 90; A65, 75; GO-300; IO-360-A, C, D, G, H, J, K; LTSIO-360-E; O-200-A, B; O-300-A, B, C, D; TSIO-360-A, B, C, D, E, F, H
SA639650	49	Continental Engines: IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; LTSIO-360-E, EB, KB; TSIO-360-A, AB, B, C, CB, D, DB, E, F, FB, G, GB, H, HB, JB, KB, LB, MB
SA639660-10KS	78	Continental Engines: GTSIO-520-D, F, H, K, L, M, N; TSIO-360-A, AB, B, C, CB, D, DB, E, F, FB, B, H, HB, JB, KB, LB, MB; TSIO-520-BE; IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; LTSIO-360-E, EB, KB
SA639660-13KS	78	Continental Engines: IO-520-A, B, BA, BB, C, CB, D, E, F, K, L, M, MB; TSIO-520-B, BB, C, D, DB, E, EB, G, H, J, JB, K, KB, L, LB, N, NB, UB, VB, WB
SA639660-14KS	78	Continental Engines: LTSIO-360-E, KB; TSIO-360-C, D, E, F, GB, KB, LB; TSIO-520-BE
SA639660-1KS	78	Continental Engines: GTSIO-520-C
SA639660-2KS	78	Continental Engines: GTSIO-520-C
SA639660-3KS	78	Continental Engines: GTSIO-520-C
SA639660-4KS	78	Continental Engines: GTSIO-520-F, K
SA639758	54	Continental Engines: IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, K; LTSIO-360-E, EB, KB; TSIO-360-A, AB, B, C, CB, D, DB, E, F, FB, G, GB, H, HB, JB, KB, LB, MB
SA640518	52	Continental Engines: O-470-K, L, R, S
SA640612	76	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-550-G; LTSIO-360-E, EB, KB; LTSIO-520-AE; TSIO-360-A, AB, B, C, CB, D, DB, E, F, FB, G, GB, H, HB, JB, KB, LB, MB; TSIO-470-B1, B2, B3, C, D; TSIO-520-AE, AF, B, BB, BE, C, CE, D, DB, E, EB, G, H,



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA641066	76	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-A, B, C, D, E, F, G, L; LTSIO-520-AE; TSIO-520-AE, AF, B, BB, BE, C, CE, D, DB, E, EB, G, H, J, JB, K, KB, L, LB, M, N, NB, P, R, T, UB, VB
SA641250	54	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-470-C, D, E, F, G, H, J, K, L, M, N, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-A, B, C, D, E, F, G, L; O-470-A, B, E, G, J, K, L, M, P, R, S, U; TSIO-520-AE, AF, B, B
SA641361	77	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-360-A, C, D, G, H, J, K; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-D, F, L, M, MB; IO-550-A, B, C, D, F, G, L; LTSIO-360-E, KB; LTSIO-520-AE; O-470-A, B, E, G, J, K, L, M, P, R
SA641368	54	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-A, B, C, D, E, F, G, L; LTSI
SA641533	78	Continental Engines: C125-2; C145-2, 2H; IO-360-H; LTSIO-360-E, EB, KB; O-300-A, B, C, D; TSIO-360-E, EB, F, FB, GB, KB, MB3
SA641538	76	Continental Engines: C125-2; C145-2, 2H; IO-360-A, C, D, G, H, J, K; LTSIO-360-E, EB, KB; O-300-A, B, C, D; TSIO-360-A, AB, B, C, CB, D, DB, E, F, FB, G, GB, H, HB, JB, KB, LB, MB; IO-360-AB, CB, DB, GB, HB, JB, KB
SA641607	90	Continental Engines: IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; LTSIO-360-E, EB, KB; TSIO-360-A, AB, B, C, CB, D, DB, E, F, FB, G, GB, H, HB, JB, KB, LB, MB
SA641651	76	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-A, G; LTSIO-360-E, EB, KB; L
SA641792	97	Continental Engines: C75-8, 12, 14, 16, 8F, 12F, 14F, 16F; C85-8, 12, 14, 16, 8F, 12F, 14F, 16F; C90-8, 12, 14, 16, 8F, 12F, 14F, 16F; C145-2, 2H; O-300-A, B, C, D; GO-300-A, C, D, E, F; O-200-A, B; C125-2
SA641793	97	Continental Engines: C75-8, 12, 14, 16, 8F, 12F, 14F, 16F; C85-8, 12, 14, 16, 8F, 12F, 14F, 16F; C90-8, 12, 14, 16, 8F, 12F, 14F, 16F; O-200-A, B; C125-2; C145-2, 2H; O-300-A, B, C, D; GO-300-A, C, D, E, F
SA641870	76	Continental Engines: C125-2; C145-2, 2H; O-300-A, B, C, D; IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; LTSIO-360-E, EB, KB; TSIO-360-A, AB, B, C, CB, D, DB, E, F, FB, G, GB, H, HB, JB, KB, LB, MB
SA641909	54	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-520-B, BA, BB, C, CB, M, MB; IO-550-A, B, C, G; TSIO-520-B, BB, BE, D, DB, E, EB, J, JB, K, KB, L, LB, N, NB, U, UB, VB, WB; TSIOL-550-A



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA641931	54	Continental Engines: O-470-A, B, E, G, J, K, L, M, P, R, S, U; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, BA, C, D, E, F, J, K, L, M; TSIO-520-B, C, D, E, G, H, J, K, L, M, N, P, R, T, U, VB, WB; GTSIO-520-C, D, F, H, K, L, M, N
SA641951	54	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; LTSIO-520-AE; TSIO-520-AE, AF, B, BB, BE, C, CE, D, DB, E, EB, G, H, J, JB, K, KB, L, LB, M, N, NB, P, R, T, UB, VB, WB
SA641973	54	Continental Engines: GTSIO-520 series
SA641992	71	Continental Engines: IO-360-AB, CB, DB, GB, HB, JB, KB; LTSIO-360-EB, KB; TSIO-360-AB, CB, DB, EB, FB, GB, HB, JB, KB, LB, MB
SA642238	76	Continental Engines: IO-520-BB, CB, MB; IO-550-A, B, G; TSIO-520-BB, BE, DB, EB, JB, KB, LB, NB, UB, VB, WB; TSIOL-550-A
SA642245	90	Continental Engines: C125-2; C145-2, 2H; IO-360-A, AB, C; LTSIO-360-E, EB, KB; O-300-A, B, C, D; TSIO-360-A, AB, B, C, CB, D, DB, E, EB, F, FB, G, GB, H, JB, KB, LB, MB
SA642249	77	Continental Engines: IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, D, E, F, J, K, L; IO-550-D, E, F, L; O-470-G; TSIO-520-AE, AF, C, CE, G, H, M, P, R, T
SA642250	77	Continental Engines: IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, D, E, F, J, K, L; IO-550-D, E, F, L; LTSIO-520-AE; O-470-G, P; TSIO-520-AE, AF, C, CE, G, H, M, P, R, T
SA642318	101	Continental Engines: TSIO-520-AE, AF, BB, C, CB, CE, G, H, M, MB, P, R, T, UB; IO-550-A, B, C, D, E, F, L; TSIOL-550-A
SA642335	54	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-A, B, C, D, E, F, G, L; LTSIO-520-AE; O-470-A, B, E, G, J, K, L, M, P, R, S, U; TSIO
SA642337	78	Continental Engines: IO-360-AB, CB, DB, GB, HB, JB, KB; LTSIO-360-EB, KB; TSIO-360-AB, CB, DB, EB, FB, GB, HB, JB, KB, LB, MB
SA642338	71	Continental Engines: IO-520-BB, CB, MB; IO-550-A, B, G; TSIO-520-BB, BE, DB, EB, JB, KB, LB, NB, UB, VB, WB; TSIOL-550-A



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA642398	54	Continental Engines: IO-520-BB, CB, MB; IO-550-A, B, C, D, E, F, G, L; TSIO-520-BB, BE, CE, DB, EB, JB, KB, LB, NB, UB, VB, WB; TSIOL-550-A
SA642714	54	Continental Engines: C75, 85, 90; IO-470-C, E, F, G, H, J, K, N, R, S; IO-520-A, B, BA, BB, D, F, J, K, L; IO-550-D, F, G, L; O-200-A, B; O-470-A, G, J, K, L, P, R, S, U; TSIO-520-AF, C, CE, D, DB, G, H, M, P, R, T, U, UB
SA642720	54	Continental Engines: IO-470-C, D, E, F, G, H, J, K, L, M, N, R, S, U, V; IO-520-A, BB, CB, D, E, F, J, K, L, MB; IO-550-A, B, C, D, E, F, G, L; O-470-A, B, E, G, J, K, L, M, P, R, S, U; TSIO-520-AE, AF, BB, BE, C, CE, DB, EB, G, H, JB, KB, LB, M, NB, P,
SA642839	54	Continental Engines: IO-520-B, BA, C, M; TSIO-520-B, D, E, J, K, L, N
SA642872	76	Continental Engines: TSIO-520-T
SA642892	78	Continental Engines: IO-550-A, B, C; LTSIO-360-E, KB; TSIO-360-E, EB, F, FB, GB, KB, LB, MB; TSIOL-550-A
SA642917-1	90	Continental Engines: IO-346-A; O-470-A, B, E, G, P, K, L, M, R, S, U; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, C, D, E, F, J, K, L, BA, BB, CB; TSIO-520-B, C, D, E, G, H, J, K, L, N, WB, UB, AF; TSIO-470-B, C, D; IO-550-B, C
SA642917-2	90	Continental Engines: TSIO-360-MB; TSIO-520-BE
SA642917-3	90	Continental Engines: TSIO-520-BE
SA643067	97	Continental Engines: O-200-A, B
SA643233	42	Continental Engines: C75; C85; C90; O-200-A, B
SA643626	71	Continental Engines: IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; O-470-U; IO-550-A, B, C, D, E, F, G, L; TSIO-520 AE, BE, CE; TSIOL-550-A



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA643629	95	Continental Engines: IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-550-A, B, C, D, E, F, G, L; C 470-A, B, E, G, J, K, L, M, P, R, S, U; TSIO-470-B, C, D; TSIO-520-AE, AF, B, BB, BE, C, CE, D, DB, E, EB, G, H, J, JB, K, KB, L, LB, M, N, NB, P
SA643766	54	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-A, B, C, D, E, F, G, L; LTSIO-520-AE; O-470-A, B, E, G, J, K, L, M, P, R, S, U; TSIO
SA643767	90	Continental Engines: E165-2; E185-1, 3, 8, 9, 11; E225-4, 8; O-470-A, B, E, G, J, K, L, M, P, R, S, U; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; TSIO-470-B, C, D; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; TSIO-520-C, G, H, M, P, R
SA643873	46	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; LTSIO-520-AE; TSIO-470-B1, B2, B3, C, D; TSIO-520-AE, AF, B, BB, BE, C, CE, D, DB, E, EB, G, H, J, JB, K, KB, L, LB, M, N, NB, P, R, T, UB, VB, WB
SA643967	54	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-470-C, D, E, F, G, H, L, M, N, P, R, S, U, V; IO-520-A, A10, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-A, B, C, D, D4, E, F, G, L; O-470-B, G, K, L, M, P, R, S, U; TSIO-360-MB; TSIO-520-AF
SA646234	90	Continental Engines: IO-470-J, K; LTSIO-520-AE; TSIO-520-AE; E165-2; E185-1, 3, 8, 9, 11; E225-4, 8; IO-346-A; O-470-A, E, J
SA646234-S		Continental Engines: IO-470-J, K; LTSIO-520-AE; TSIO-520-AE; E165-2; E185-1, 3, 8, 9, 11; E225-4, 8; IO-346-A; O-470-A, E, J
SA646254	76	Continental Engines: LTSIO-360-E, KB; TSIO-360-A, B, C, D, E, F, GB, H, JB, KB, LB, MB
SA646277	77	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-A, B, C, D, E, F, G, L; O-470-A, B, E, G, J, K, L, M, P, R, S, U, U11, U12; TSIO-520
SA646288	63	Continental Engines: IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; IO-470-C, D, E, F, G, H, J, K, L, M, N, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-A, B, C, D, E, F, G, L; LTSIO-360-E, EB, KB; O-470-A, B, E, G, J,
SA646303	55	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; TSIO-520-B, BB, BE, C, CE, D, DB, E, EB, G, H, J, JB, K, KB, L, LB, M, N, NB, P, R, T, U, UB, VB, WB
SA646459	78	Continental Engines: IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; LTSIO-360-E, EB; TSIO-360-A, AB, B, C, CB, D, DB, E, EB, F, FB, G, GB, H, HB, JB, KB, LB, MB



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA646460	78	Continental Engines: IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; LTSIO-360-E, EB, KB; TSIO-360-A, AB, B, C, CB, D, DB, E, EB, F, FB, G, GB, H, HB, JB, KB, LB, MB
SA646605	77	Continental Engines: C75; C85; C90; GTSIO-520-C, D, F, H, K, L, M, N; IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; IO-470-C, D, E, F, F19, F23, F3, F4, F5, F7, G, H, J, K, K14, L, M, N, P, R, S, S8, U, V; IO-520-A, B, BA, BB, C, CB, D, D32, D3
SA646743	78	Continental Engines: LTSIO-360-E, EB, KB; TSIO-360-A, AB, B, C, CB, D, DB, E, EB, F, FB, GB, H, HB, JB, KB, LB, MB; LTSIO-360-E, KB
SA646846	137	Continental Engines: A-65; C-75; C-85; C-90; E-225; C-125; C-145; O-200-A, B, C, D; O-300-A, B, C, D; GO-300-A, C, D, E
SA646985	77	Continental Engines: IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-550-A, B, C, D, E, F, L; O-470-A, B, E, G, J, K, L, M, P, S, V; TSIOL-550-A; IO-520-A, BA, C, D, E, F, J, K, L, M; TSIO-520-AE, AF, B, BB, C, CE, D, DB, E, EB, G, H, J, JB, K,
SA648013	95	Continental Engines: IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB
SA648029	138	Continental Engines: O-470-U; IO-470-D, E, F, H, L, M, N, S, U, V
SA648044	147	Continental Engines: TSIO-520-AF, B, BB, BE, C, CE, D, DB, E, EB, G, H, J, JB, K, KB, L, LB, M, N, NB, P, R, T, UB, VB, WB
SA649205	95	Continental Engines: IO-520-BA, BB, C, CB, M, MB; IO-550-A, B, C, G; TSIO-520-B, BB, BE, D, DB, E, EB, J, JB, K, KB, L, LB, N, NB, UB, VB, WB; TSIOL-550-A
SA649506	86	Continental Engines: C125-2; C145-2, 2H; IO-360-A, AB, B, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; O-300-A, B, C, D; TSIO-360-A, AB, B, C, CB, D, DB, E, EB, F, FB, G, GB, H, HB, J, JB, K, KB, LB, MB; LTSIO-360-E, KB
SA649520		Continental Engines: IO-520-B, BA, BB, C, CB, M, MB; TSIO-520-B, BB, BE, D, DB, E, EB, J, JB, K, KB, L, LB, N, NB, UB, VB, WB; IO-550-B, C
SA649520-A3	137	Continental Engines: IO-520-B, BA, BB, C, CB, M, MB; TSIO-520-B, BB, BE, D, DB, E, EB, J, JB, K, KB, L, LB, N, NB, UB, VB, WB; IO-550-B, C



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA65000S0	148	Continental Engines: A-65-1, A-65-3, A65-6, A65-7, A65-8, A65-9, A65-12, A65-14
SA652541	147	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-A, B, C, G; LTSIO-520-AE; O-470-A, B, E, G, J, K, L, M, P, R, S, U; TSIO-520-AE, AF,
SA652947	110	Continental Engines: IO-470-C, D, E, F, G, H, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; O-470-B, G, K, L, M, P, R, S, U; TSIO-470-B, C, D; TSIO-520-AF, B, BB, C, CE, D, DB, E, EB, G, H, J, JB, K, KB, L, LB, M, N, NB, P,
SA652984	99	Continental Engines: IO-470-C, D, E, F, G, H, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; O-470-B, G, K, L, M, P, R, S, U; TSIO-470-B1, B2, B3, C, D; TSIO-520-AF, B, BB, C, CE, D, DB, E, EB, G, H, J, JB, K, KB, L, LB, M,
SA653359	153	Continental Engines: IO-346; IO-520-B, BA, BB, C, CB, M, MB; IO-550-A, B, C, G; TSIO-520-B, BB, D, DB, E, EB, J, JB, K, KB, L, LB, N, NB, U, UB, V, VB, W, WB; TSIOL-550-A, B; TSIO-550-B
SAC10203		Continental Engines: C75-8, 12, 14, 16, 8F, 12F, 14F, 16F; C85-8, 12, 14, 16, 8F, 12F, 14F, 16F; C90-8, 12, 14, 16, 8F, 12F, 14F, 16F; O-200-A, B; C125-2; C145-2, 2H; O-300-A, B, C, D; GO-300-A, C, D, E, F
SAF10202		Continental Engines: C75-8, 12, 14, 16, 8F, 12F, 14F, 16F; C85-12, 14, 16, 8F, 12F, 14F, 16F; C90-8, 12, 14, 16, 8F, 12F, 14F, 16F; O-200-A, B; C125-2; C145-2, 2H; O-300-A, B, C, D; GO-300-A, C, D, E, F